

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21004762/T1TF3Q2
Date: 19/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070179132
Claimant Vehicle No :	FBP6734T	Insured Vehicle No :	GBJ1451Z
Date of Loss:	09/04/2021	Nature of Claim:	TP
		Claim No:	7127758727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP6734T	Engine No:	KC32E0023903
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	MLHKC2882J5023903
Reg. Date:	17/05/2019 (Man. Year: 2018)	Odometer:	37052 km
Colour:	Green		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

5/19/2021

Adjuster Report

Date of Assignment: 15/04/2021

Date Inspected: 15/04/2021 Inspected At:

Equator Brotherhood (HQ)
25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB
SINGAPORE 417800

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/19/2021

Adjuster Report

MARKET VALUE: \$10,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT TYRE	Cut	0.00 F	*- F
3	1		*FRONT RIM	Bent	0.00 F	*- F
4	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
5	1		*FRONT FORK ASSY	*Check	0.00 F	*- F
6	1		*FRONT HEADLAMP RIM	Cracked	0.00 F	*- F
7	1		*FRONT HEADLAMP	Cut	0.00 F	*- F
8	1		*FRONT HEADLAMP BRACKET	Cracked	0.00 F	*- F
9	1		*FRONT WING MIRROR	Missing	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
11	1		*METER BRACKET	Bent	0.00 F	*- F
12	1		*METER ASSY	Cut	0.00 F	*- F
13	1		*ERP BRACKET	Bent	0.00 F	*- F
14	1		*ERP UNIT	Cut	0.00 F	*- F
15	1		*STEERING CONE & BEARING	*Check	0.00 F	*- F
16	1		*HANDLE BAR	Bent	0.00 F	*- F
17	1		*HANDLE BAR GRIP	Torn	0.00 F	*- F
18	1		*HANDLE BAR BALANCER LH	Bent	0.00 F	*- F
19	1		*FUEL TANK COVER	Cracked	0.00 F	*- F
20	1		*CLUTCH LEVER	Dented	0.00 F	*- F
21	1		*FRT SIDE COVER LH (GREY)	Cut	0.00 F	*- F
22	1		*SIDE COVER LH (GREY)	Cut	0.00 F	*- F
23	1		*FRONT FOOT REST	Dented	0.00 F	*- F
24	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
25	1		*FOOT GEAR SHIFLET	Bent	0.00 F	*- F
26	1		*REAR LH SIGNAL LAMP	Cut	0.00 F	*- F
27	1		*REAR BOX	Cut	0.00 F	*- F
28	1		*REAR BOX BRACKET	*Check	0.00 F	*- F
29	1		*STICKER	Necessary	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >