

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19009064/T1QF3E2-1

**Date:** 21/04/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29120056MCX
<b>Claimant Vehicle No :</b>	SJU3326L	<b>Insured Vehicle No :</b>	SMK9150D
Date of Loss:	14/05/2019	Nature of Claim:	TP
		Claim No:	594159

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJU3326L</b>	Engine No:	A769I574N46B20BZ
Make & Model:	BMW 318I, 2.0 L (A)	Chassis No:	WBAPF72060A143478
Reg. Date:	30/11/2009 (Man. Year: 2009)	Odometer:	187974 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,025.29	3,687.71	3,337.58	47.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	830.00	980.00	54.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,835.29</b>	<b>4,517.71</b>	<b>4,317.58</b>	<b>48.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	8,835.29	3,600.00	5,235.29	59.25
<b>+ GST 7.00/7.00% (S\$)</b>	618.47	252.00	366.47	59.25
<b>Nett Amount (S\$)</b>	<b>9,453.76</b>	<b>3,852.00</b>	<b>5,601.76</b>	<b>59.25</b>

### INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	14/06/2019	Inspected At: My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2021)
<b>Parts:</b>	143	BMW 318i 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU3326L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,259.30 FL	*1,105.15 FL
2	2		*FRONT BUMPER RETAINER	Necessary	270.10 FL	*270.10 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	700.72 FL	*575.30 FL
4	1		*FRONT BUMPER TOW COVER	Deformed	55.00 FL	*55.00 FL
5	1		*FRONT BUMPER GRILLE LH	Cracked	155.70 FL	*155.70 FL
6	1		*FRONT BUMPER GRILLE RH	Cracked	155.70 FL	*155.70 FL
7	1		*FRONT BUMPER SIDE COVER RH	Cracked	74.75 FL	*74.75 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	125.47 FL	*125.47 FL
9	1		*FRONT RH HEADLAMP	Cracked	2,200.31 FL	*1,250.00 FL
10	1		*FRONT RH HEADLAMP BRACKET	Necessary	62.00 FL	*62.00 FL
11	1		*FRONT LH HEADLAMP	Not Necessary	2,200.31 FL	*- FL
12	1		*FRONT LH HEADLAMP BRACKET	Not Necessary	62.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
14	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,391.36</b>	<b>3,879.17</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$)</b>	366.07	191.46
<b>Total Parts (\$)</b>	<b>7,025.29</b>	<b>3,687.71</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	300.00	200.00
3	PANEL BEATING ON AFFECTED AREAS	New	700.00	300.00
4	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	300.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>1,810.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >