

HP:9888 8885 ( Jeremy )

Authorised Signatory

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

---

Our Ref: WG/TP/2019-238  
Invoice No: TP/MCC/2019-238  
Vehicle No: SJU3326L  
Attn: LEE KHAI ANG  
Company: MY CAR CONSULTANT PTE LTD  
Address: 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

Date 17 July 2019

## *Invoice*

Surveyor Fee:	S\$250
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$31/- (@ \$1 per photo, total 31 photos)
Total:	S\$381

Surveyor:  
Signature:  
Date:



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : LEE KHAI ANG  
C/O MY CAR CONSULTANT PTE LTD  
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park  
Singapore 408934

Date : 17 July 2019  
Our Ref : WG/TP/2019-238

### REFERENCE PARTICULARS

Date of Accident : 14 May 2019  
Date of Inspection : 18 June 2019

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 18 June 2019

### VEHICLE PARTICULARS

Registration No : SJU3326L  
Make : B.M.W.  
Model : 318i 2.0L A/T ABS D/AIRBAG 2WD  
Year : 2009

Engine No : A7691574N46B20BZ  
Chassis No : WBAPF72060A143478  
Odometer : 187974km  
Colour : Green

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front Near side	: Pirelli	205/55R16	5 mm
Front Off Side	: Pirelli	205/55R16	5 mm
Rear Near Side	: Pirelli	205/55R16	5 mm
Rear off Side	: Pirelli	205/55R16	5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was **S\$5,100.00** nett at lump sum basis. (Subject to GST if applicable)  
Under normal circumstances, estimated period required for repairs : Five ( 05 ) working days.

Enclosed Thirty-one ( 31 ) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD  
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

In accordance to your instruction, we have **not** authorise repairs and inspection was conducted strictly on a "**WITHOUT PREJUDICE BASIS**".

VEHICLE NO : SJU3326L  
MODEL :318I 2.0L A/T ABS D/AIRBAG 2WD 4DR

Our Ref : WG/TP/2019-238

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

	QTY	ASSESSED	ORIGINAL	REVISED
SPARE PARTS	PC/SET	CONDITION	QUOTATION	QUOTATION
1 FRONT BUMPER	1	DEFORMED	\$ 1,259.30	\$ 1,259.30
2 FRONT BUMPER RETAINER	2	NECESSARY	\$ 270.10	\$ 270.10
3 FRONT BUMPER REINFORCEMENT	1	DENTED	\$ 700.72	\$ 700.72
4 FRONT BUMPER TOW COVER	1	DEFORMED	\$ 55.00	\$ 55.00
5 FRONT BUMPER GRILLE LH	1	CRACKED	\$ 155.70	\$ 155.70
6 FRONT BUMPER GRILLE RH	1	CRACKED	\$ 155.70	\$ 155.70
7 FRONT BUMPER SIDE COVER RH	1	CRACKED	\$ 74.75	\$ 74.75
8 FRONT BUMPER LOWER GRILLE	1	CRACKED	\$ 125.47	\$ 125.47
9 FRONT RH HEADLAMP	1	CRACKED	\$ 2,200.31	\$ 2,200.31
10 FRONT RH HEADLAMP BRACKET	1	NECESSARY	\$ 62.00	\$ 62.00
11 FRONT LH HEADLAMP	1	NOT NECESSARY	\$ 2,200.31	\$ -
12 FRONT LH HEADLAMP BRACKET	1	NOT NECESSARY	\$ 62.00	\$ -
			\$ 7,321.36	\$ 5,059.05
		Less 5%	\$ 366.06	\$ 252.95
			\$ 6,955.30	\$ 4,806.10
B) <u>S/NETT ITEM</u>				
13 FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 40.00	\$ 30.00
14 FRONT GRILLE CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
			\$ 70.00	\$ 50.00
		Parts Total :	\$ 7,025.30	\$ 4,856.10
C) <u>LABOUR CHARGES &amp; MISC</u>				
15 CHECK FRONT WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00
16 DIAGNOIS CHECK AND CLEAR FAULT CODE			\$ 300.00	\$ 250.00
17 PANEL BEATING ON AFFECTED AREAS			\$ 700.00	\$ 600.00
18 SPRAY PAINTING ON AFFECTED AREAS			\$ 600.00	\$ 500.00
19 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 120.00
		Labour Total :	\$ 1,810.00	\$ 1,520.00
		Total Parts and Laboure :	\$ 8,835.30	\$ 6,376.10
<u>FINAL LUMP SUM ADJUSTMENT</u>				<u>\$ 5,100.00</u>

#### POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.


#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$5,100.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES



---

Winsen Goh  
Automotive Appraiser