

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21004770/KYA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100469715
Claimant Vehicle No :	SJS5570U	Insured Vehicle No :	SDW6669M
Date of Loss:	11/04/2021	Nature of Claim:	TP
		Claim No:	9252082829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS5570U	Engine No:	HIDDEN
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305124263
Reg. Date:	01/08/2009 (Man. Year: 2009)	Odometer:	397254 km
Colour:	Metallic Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Arivo 9 mm	Rear Left Side:	Arivo 9 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Arivo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,222.20	200.00	1,022.20	83.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	660.00	280.00	29.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,162.20	860.00	1,302.20	60.23
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/04/2021	
Date Inspected:	14/04/2021	Inspected At: City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	398.20 FL	*- FL
2	1		*FRONT BUMPER RETAINER -LH	Serviceable	53.10 FL	*- FL
3	1		*FRONT FENDER -LH	Repair	594.50 FL	*- FL
4	1		*WHEEL BEARING	*Check	183.80 FL	*- FL
5	1		*RIM	Dented	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	1,529.60 200.00
					- List Item Discount on L Items 25.00/25.00% (\$)	307.40 0.00
					Total Parts (\$)	1,222.20 200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
2	TO CHARGE WHEEL BEARING (*Check)	New	80.00	0.00
3	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	200.00	200.00
4	SPRAY PAINTING ON AFFECTED & REPLACED PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			940.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >