

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBK 1900P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH EXTENSION WHEEL HOUSING STRUT (SN)	BENT	170.45	170.45
1	RH FOG LAMP SUPPORT (SN)	NOT NECESSARY	78.45	-
1	IMPACT ABSORBER TOP (SN)	NOT NECESSARY	49.50	-
1	FRT BUMPER PRIMED PANEL (PMA)(SN)	DEFORMED	901.75	901.75
2	GROMMET (SN)	NOT NECESSARY	1.60	-
1	LH SUPPORT HEADLIGHT ARM (SN)	BENT	124.05	124.05
1	PLAQUE 82MM (SN)	NECESSARY	71.95	71.95
1	LH HEADLIGHT LED TECHNOLOGY (SN)	CRACKED	2,359.75	2,359.75
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			3,837.50	3,707.95
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER,FRONT LEFT SUPPORTING STRUT,LEFT HEADLIGHT SUPPORT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.		2,125.00	1,700.00
	TO RESPRAY FRONT BUMPER.		1,038.00	986.00
	TO REPLACE LEFT HEADLIGHT.		481.00	456.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	168.00
			3,998.00	3,478.00
	GRAND TOTAL		7,835.50	7,185.95

RECOMMENDED COST OF REPAIRS		7,185.95

Report Ref No. CS/GAI21004774/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.