



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6571D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	CRACKED	430.90	430.90
1	FRONT BUMPER BRACKET RH	DEFORMED	35.00	35.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT EMBLEM-BLUE DRIVE	NECESSARY	26.60	26.60
1	FRONT BUMPER CENTRE MOULDING	NOT NECESSARY	368.50	-
1	FRONT WHEEL RIM	NOT NECESSARY	1,124.20	-
1	HEAD LAMP ASSY RH	NOT NECESSARY	1,993.65	-
1	FRONT DAY LIGHT RH	CUT	642.50	642.50
1	FRONT BUMPER GRILLE RH	CRACKED	186.90	186.90
	LESS 20% DISCOUNT		-1,079.41	-264.38
			4,317.64	1,057.52
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER ADVERTISEMENT (SN)	CUT	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	350.00
	SPRAY PAINT.		600.00	500.00
	CHECK LIGHTING.		60.00	30.00
			1,460.00	880.00
GRAND TOTAL			5,877.64	2,037.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. NS/INC21004786/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.