

# **AIR ESTIMATE\***

VEHICLE NO SHD3009R  
MAKE HYUNDAI  
MODEL I-40

DATE 10/04/21 12:00 AM  
MVA CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT WING MIRROR LH			\$670.00
1	REAR TYRE RIM LH			\$650.60
1	REAR WHEEL CAP LH			\$214.20
	<b>SUB TOTAL</b>		884.20	<b>\$1,534.80</b>
	<b>20.00%</b>		707.36	<b>\$306.96</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,227.84</b>
1	REAR TYRE LH 10%		172.80	<b>\$216.00</b>
1	REAR DOOR COMFORT APP STICKER 10%		252.80	<b>\$80.00</b>
			227.52	<b>\$266.40</b>
	<b>Labour Charge</b>			
	Panel Beating		420.00	\$600.00
	Spray Painting Charge		750.00	\$800.00
	Remove/refix rear under carriage		nn	\$90.00
	Tuff coat		nn	\$90.00
	Check Lighting		30	\$60.00
	<b>TOTAL LABOUR</b>		1200	<b>\$1,640.00</b>
	<b>ESTIMATE TOTAL</b>		2134.88	<b>\$3,134.24</b>
			4541700	
			3 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 97415744  
'wp' 13/4/21 @ 12pm  
t/s Resurvey after repair  
Tanpin e / kh auto.com  
2-3 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: