

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4399T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR PANEL GARNISH	NOT NECESSARY	57.50	-
1	REAR END PANEL	NOT NECESSARY	526.70	-
1	REAR PANEL LOWER	NOT NECESSARY	495.50	-
2	REAR BUMPER REFLECTOR LH/RH @\$32.00	NOT NECESSARY	64.00	-
	LESS 20% DISCOUNT		-593.14	-271.20
			2,372.56	1,084.80
	NETT ITEMS			
1	REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	280.00
	SPRAY PAINTING CHARGE.		500.00	250.00
	CHECK LIGHTING.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
			1,370.00	560.00
	GRAND TOTAL		3,914.69	1,816.93





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,450.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21004793/T1vcn2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**