



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 3507D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	900.00	581.00
1	FRONT HEADLAMP (N/S)	CRACKED	850.00	625.00
1	FRONT HEADLAMP (O/S)	CUT	850.00	625.00
1	FRONT BUMPER RE-INFORCEMENT FOAM	BROKEN	280.00	186.00
1	FRONT BUMPER GRILLE	BROKEN	320.00	320.00
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	480.00	-
	LESS 10% DISCOUNT		-368.00	-
	LESS 25% DISCOUNT		-	-584.25
			3,312.00	1,752.75
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER RETAINER (SN)	BROKEN	60.00	60.00
1	FRONT FOG LAMP BULB (SN)	NOT NECESSARY	20.00	-
			80.00	60.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE, REFIT, AND RE-ALIGNMENT OF ALL DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER.		800.00	250.00
	TO PROVIDE SPRAY PAINTING WORKS TO AFFECTED AREAS IE : BUMPER, FENDER.		500.00	400.00
	ELECTRICAL TESTING FOR ALL AFFECTED ELECTRICAL COMPONENTS.		30.00	30.00
			1,330.00	680.00
	GRAND TOTAL		4,722.00	2,492.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS3/AGI21001667/Eqd3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.