

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19960/196R GS1 Reg. No. 19-960/196-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI21004798/Kvf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 30/04/2021	
			Co	ode: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKA 3103G	Veh. Inspected	SBL 9899C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10009828/CH	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	16/04/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JTEKB3GH80J002942	Colour	METALLIC SILVER	
	Odometer	48029 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/55 R18	MICHELIN	7 mm	
	L/H Front Tyre	235/55 R18	MICHELIN	7 mm	
	R/H Rear Tyre	235/55 R18	MICHELIN	7 mm	
	L/H Rear Tyre	235/55 R18	MICHELIN	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	13/04/2021	Inspection Date	16/04/2021	
	Survey held at	COMPLETE VMS PTE LTD			
		BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPL	EX SINGAPORE 5757	21	
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: