

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004802/T1TF3Q2
Date: 29/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900253224
Claimant Vehicle No :	SFM8121S	Insured Vehicle No :	SLU8377H
Date of Loss:	10/04/2021	Nature of Claim:	TP
		Claim No:	8732564805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFM8121S	Engine No:	3ZRB674142
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	ZSU600063257
Reg. Date:	12/01/2016 (Man. Year: 2015)	Odometer:	102428 km
Colour:	Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/29/2021

Adjuster Report

Date of Assignment: 16/04/2021

Date Inspected: 20/04/2021

Inspected At:

Paul Hoe Batteries & Motor Services (HQ)
1 KAKI BUKIT AVE 6 #01-109
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/29/2021

Adjuster Report

MARKET VALUE:\$80,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	Deformed	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*FRT BUMPER LOWER SPOILER	Deformed	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
8	1		*FRT LH FOG LAMP	*Check	0.00 F	*- F
9	1		*FRT LH FOG LAMP GARNISH	Deformed	0.00 F	*- F
10	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
11	1		*FRT LH LOWER ARM	*Check	0.00 F	*- F
12	1		*FRT LH KNUCKLE ARM	Bent	0.00 F	*- F
13	1		*FRT LH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
14	1		*FRT LH SHOCK ABSORBER	*Check	0.00 F	*- F
15	1		*FRT HEADLAMP LH	Cut	0.00 F	*- F
16	1		*FRT HEADLAMP LH BRACKET	Deformed	0.00 F	*- F
17	1		*FRT LH FENDER	Repair	0.00 F	*- F
18	1		*FRT LH FENDER INNER SHIELD	*Check	0.00 F	*- F
19	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >