



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 6692G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER - RH (SN)	BUCKLED	450.00	450.00
1	FRONT FENDER INNER SHIELD - RH (SN)	DISTORTED	150.00	150.00
1	FRONT BUMPER (SN)	BUCKLED	1,075.00	1,075.00
1	FRONT BUMPER BRACKET - RH (SN)	* CHECK	38.00	-
1	SET OF FRONT BUMPER CLIPS (SN) (NPA)	* CHECK	-	-
1	FRONT BUMPER RETAINER - RH (SN)	DISTORTED	25.00	25.00
1	HEADLIGHT - RH (SN) (NPA)	* CHECK	-	-
1	SUNDRIES (SN)	* CHECK	200.00	-
			1,938.00	1,700.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND HEADLIGHT WASHER ASSY.	NOT NECESSARY	280.00	-
	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	* CHECK	200.00	-
	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		1,200.00	800.00
	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.		1,600.00	800.00
	TO CARRY OUT DIAGNOSTIC CHECK.	NOT NECESSARY	192.00	-
			3,472.00	1,600.00
<b>GRAND TOTAL</b>			<b>5,410.00</b>	<b>3,300.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$438.00 NETT)</b>				<b>3,300.00</b>

Report Ref No. CS/SMO21004804/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.