

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004805/ATF3N2**Date:** 14/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00011042100

Claimant Vehicle No : SLJ8934H **Insured Vehicle No :** GBH1772H

Date of Loss: 02/04/2021 Nature of Claim: TP Claim No: SNM21D201913/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ8934H**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B5000330

Reg. Date: 29/12/2016 (Man. Year: 2016) Chassis No: GK81100292

Colour: White Odometer: 115668 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,251.04	5,149.76	5,101.28	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,990.00	1,160.00	27.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,401.04	8,139.76	6,261.28	43.48
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	14,401.04	6,500.00	7,901.04	54.86

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 16/04/2021 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jan 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8934H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,218.70 FL	*1,150.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH & RH	O/s Damaged	136.40 FL	*68.20 FL
3	1		*REAR BUMPER SIDE GARNISH LH & RH	O/s Cracked	208.20 FL	*104.10 FL
4	2		*REAR BUMPER BRACKET LH & RH	Not Necessary	171.20 FL	*- FL
5	1		*REAR BUMPER SPONGE LH & RH	O/s Cracked	207.00 FL	*103.50 FL
6	1		*REAR BUMPER LOWER REFLECTOR COVER RH	Cracked	110.00 FL	*110.00 FL
7	1		*REAR BUMPER TOW COVER	Not Necessary	40.00 FL	*- FL
8	1		*REAR TAILGATE	Dented	1,292.70 FL	*1,193.00 FL
9	1		*REAR TAILGATE INNER LOCK	Not Necessary	378.00 FL	*- FL
10	1		*REAR TAILGATE INNER TRIMBOARD	Cracked	410.00 FL	*320.00 FL
11	2		*REAR TAILGATE DAMPER LH & RH	Not Necessary	600.00 FL	*- FL
12	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	72.00 FL	*72.00 FL
13	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	80.10 FL	*80.10 FL
14	1		*REAR TAILGATE LOGO	Not Necessary	75.00 FL	*- FL
15	1		*REAR TAILGATE CENTRE CHROME	Not Necessary	405.00 FL	*- FL
16	1		*REAR TAILGATE WEATHERSTRIP	Cut	232.80 FL	*232.80 FL
17	2		*REAR TAILGATE LAMP RH	Cracked	444.50 FL	*444.50 FL
18	2		*REAR TAILLAMP RH	Cracked	578.00 FL	*578.00 FL
19	1		*REAR END PANEL	Dented	620.00 FL	*620.00 FL
20	1		*REAR SPARE TYRE WELL PANEL	Repair	1,003.80 FL	*- FL
21	1		*REAR SPARE TYRE BOARD	Not Necessary	687.80 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
23	1		*REAR FENDER RH	Repair	1,280.00 FL	*- FL
24	1		*REAR FENDER TRIM BOARD RH	Cracked	549.60 FL	*498.00 FL
25	1		*REAR TAILGATE UPPER SPOILER	Not Necessary	850.00 FL	*- FL
26	1		*TAILLAMP PANEL RH	Dented	268.00 FL	*268.00 FL
27	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
30	1		*SET REAR TAILGATE INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,658.80	6,342.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,407.76	1,192.44
Total Parts (\$\$)	10,251.04	5,149.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	1,200.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	1,200.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	120.00
5	TO REMOVE AND REPLACE REVERSE SENSOR AND REVERSE CAMERA AND CHECJ FOR PROPER FUNCTION	New	150.00	100.00
6	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
7	TO CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
8	TO TRANSFER REAR BOOT MECHANISM	New	120.00	80.00
9	TO TUFF COAT	New	150.00	60.00
10	TO REMOVE AND REFIX REAR SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD	New	180.00	80.00
Gross Labour Cost (\$\$)			4,150.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >