

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21004806/EQF3N2**Date:** 03/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00048542000

**Claimant Vehicle No :** PZ6H **Insured Vehicle No :** YN8369P

Date of Loss: 09/04/2021 Nature of Claim: TP Claim No: SNM21D202152/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PZ6H**

Make & Model: SCANIA KIB4X2, 12.7 D (M) Engine No: 6817961

Reg. Date: 30/04/2015 (Man. Year: 2014) Chassis No: YS2K4X20001890430

Colour: Multi-colour Odometer: 426259 km

Engine Capacity: 12742 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,005.00	5,982.00	4,023.00	40.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,280.00	2,800.00	3,480.00	55.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,285.00</b>	<b>8,782.00</b>	<b>7,503.00</b>	<b>46.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,000.00</b>		
<b>(S\$)</b>	16,285.00	7,000.00	9,285.00	57.02
<b>+ GST 7.00/7.00% (S\$)</b>	1,139.95	490.00	649.95	57.02
<b>Nett Amount (S\$)</b>	<b>17,424.95</b>	<b>7,490.00</b>	<b>9,934.95</b>	<b>57.02</b>

**INSPECTION**

Date of Assignment: 16/04/2021

Date Inspected: 22/04/2021 Inspected At: Crown Asia Bus Builder Pte Ltd (HQ)  
NO. 44 SUNGEI KADUT STREET 1  
Singapore 729349

Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 Dec 2021)	
<b>Parts:</b>	N/A	SCANIA KIB4X2 12.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PZ6H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR ENGINE COVER PANEL	Broken	2,800.00 FL	*2,000.00 FL
2	1		*REAR ENGINE TOP COVER PANEL	Dented	1,600.00 FL	*1,550.00 FL
3	1		*REAR LEFT TAILLAMP	Broken	1,100.00 FL	*780.00 FL
4	1		*REAR LEFT TAILLAMP PANEL	Broken	3,200.00 FL	*1,800.00 FL
5	1		*REAR LEFT SIDE PANEL	Bent	2,400.00 FL	*500.00 FL
6	1		*60KM/H STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,115.00</b>	<b>6,645.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,110.00	663.00
<b>Total Parts (\$\$)</b>	<b>10,005.00</b>	<b>5,982.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	POLYURETHANE FOAM SPRAY SET (IMPORTED FROM U.S.A)	New	1,000.00	400.00
2	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS & COMPONENTS	New	2,000.00	1,400.00
3	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RE-SPRAY PAINT ON PARTS REPLACED	New	2,400.00	800.00
4	TO CHECK ELECTRICAL WIRING AT DAMAGE AREAS	New	180.00	50.00
5	TO RESET AND PROGRAM COMPUTER SETTING	New	350.00	100.00
6	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	350.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,280.00</b>	<b>2,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >