



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 522Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
4	REVERSE SENSOR @\$80.00	SERVICEABLE	320.00	-
1	REAR BUMPER	CRACKED	1,837.50	1,837.50
1	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	47.50	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	47.50	47.50
1	REAR BUMPER SIDE GARNISH RH	SERVICEABLE	105.00	-
1	TAIL LAMP RH	CUT	875.00	875.00
1	RH REAR RIM	DENTED	550.00	550.00
1	RH REAR TYRE	SERVICEABLE	350.00	-
1	RHS SKIRT	MISSING	580.00	580.00
	LESS 10% DISCOUNT		-474.25	-392.00
			4,268.25	3,528.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,RHR FENDER,RHS SKIRT).		800.00	560.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,RHR FENDER,RHS SKIRT).		800.00	660.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	60.00
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM,TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
			2,160.00	1,380.00
	GRAND TOTAL		6,428.25	4,908.00

Report Ref No. CS/SMO21004813/Ktf3e2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			4,908.00
---	--	--	-----------------

Report Ref No. CS/SMO21004813/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.