

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21004816/GQF3E2

Date: 19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800053293
Claimant Vehicle No : SJU5587L **Insured Vehicle No :** SLZ3168B
Date of Loss: 13/04/2021 Nature of Claim: TP Claim No: 5874682174SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU5587L**
Make & Model: MITSUBISHI LANCER, 1.6 GLX 5MT AIRBAG 2WD (M) Engine No: 4G18KC7905
Reg. Date: 16/12/2009 (Man. Year: 2009) Chassis No: JMYSNCS3A9U004755
Colour: White Odometer: 291402 km
Engine Capacity: 1584 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R16 Rear Tyre Size: 205/45 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/04/2021
Date Inspected: 16/04/2021 Inspected At: Nexpress Performance Pte Ltd (HQ)
25, Kaki Bukit Road 4, Synergy @ KB, #01-39,
Singapore 417800 Contact: Mr Pan(Ah Nam)
82170834
Singapore 417800
Estimated Period of Repair: 13.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$28,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Distorted	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Cracked	0.00 F	*- F
4	1		*FRT BUMPER	Dented	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Distorted	0.00 F	*- F
8	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
9	1		*FRT BUMPER LOWER SPOILER	Distorted	0.00 F	*- F
10	1		*FRT LH BUMPER FOG LAMP COVER	* Check	0.00 F	*- F
11	1		*FRT RH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
12	1		*FRT GRILLE	Cracked	0.00 F	*- F
13	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
14	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
15	1		*HORN	* Check	0.00 F	*- F
16	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
17	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
18	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
19	1		*BONNET	Buckled	0.00 F	*- F
20	1		*BONNET LOCK	Jammed	0.00 F	*- F
21	1		*BONNET INSULATOR	Bent	0.00 F	*- F
22	2		*BONNET HINGE	Bent	0.00 F	*- F
23	1		*BONNET RUBBER	* Check	0.00 F	*- F
24	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
25	1		*AIR CON FAN ASSY	* Check	0.00 F	*- F
26	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	* Check	0.00 F	*- F
27	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	* Check	0.00 F	*- F
28	1		*AIR CON DISCHARGE HOSE	* Check	0.00 F	*- F
29	1		*AIR CON LIQUID PIPE	* Check	0.00 F	*- F
30	1		*RADIATOR	* Check	0.00 F	*- F
31	1		*RADIATOR COWLING	* Check	0.00 F	*- F
32	1		*RADIATOR FAN ASSY	* Check	0.00 F	*- F
33	1		*RADIATOR HOSE TOP	* Check	0.00 F	*- F
34	1		*RADIATOR EXPANSION TANK	* Check	0.00 F	*- F
35	1		*AIR DUCT	* Check	0.00 F	*- F
36	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
37	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
38	1		*FRT RH FENDER	Buckled	0.00 F	*- F
39	1		*FRT RH FENDER INNER SHIELD	* Check	0.00 F	*- F
40	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
41	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
42	1		*FRT RH DOOR	Repair	0.00 F	*- F
43	1		*REAR NUMBER PLATE	Distorted	0.00 F	*- F
44	1		*REAR NUMBER PLATE GARNISH	Distorted	0.00 F	*- F
45	1		*REAR BUMPER	Bent	0.00 F	*- F
46	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
47	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
48	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
49	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
50	1		*REAR BUMPER LOWER SPOILER	Bent	0.00 F	*- F
51	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
52	1		*REAR END PANEL	Buckled	0.00 F	*- F
53	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
54	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
55	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR RH TAILLAMP PANEL	Buckled	0.00 F	*- F
57	1		*BOOTLID	Buckled	0.00 F	*- F
58	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
59	1		*BOOTLID LOCK	Distorted	0.00 F	*- F
60	1		*BOOTLID RUBBER	Dented	0.00 F	*- F
61	1		*BOOTLID HINGE	Bent	0.00 F	*- F
62	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
63	1		*SPARE TYRE COVER	* Check	0.00 F	*- F
64	1		*CENTRE EXHAUST PIPE ASSY	* Check	0.00 F	*- F
65	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
66	2		*REAR EXHAUST MOUNTING	Bent	0.00 F	*- F
67	1		*REAR RH FENDER	Buckled	0.00 F	*- F
68	1		*REAR RH FENDER INNER TRIM	Torn	0.00 F	*- F
69	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
70	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
71	1		*REAR FENDER AIR GRILLE RH	Bent	0.00 F	*- F
72	1		*REAR RH DOOR LOCK	Jammed	0.00 F	*- F
73	1		*REAR RH DOOR RUBBER	Dented	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >