

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21004825/KPA3Q2
Date: 23/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800152723
Claimant Vehicle No :	SGR3056S	Insured Vehicle No :	EC49K
Date of Loss:	09/04/2021	Nature of Claim:	TP
		Claim No:	3934952889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR3056S		
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Engine No:	1AZE018773
Reg. Date:	06/02/2007 (Man. Year: 2006)	Chassis No:	MR053BK4107005506
Colour:	Metallic Green	Odometer:	207933 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55Z R17	Rear Tyre Size:	225/55Z R17
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,690.81	1,868.57	822.24	30.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,160.00	1,160.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,010.81	3,028.57	1,982.24	39.56
Approved Total (Overridden) (S\$)		2,400.00		

(S\$)	5,010.81	2,400.00	2,610.81	52.10
+ GST 7.00/7.00% (S\$)	350.76	168.00	182.76	52.10
Nett Amount (S\$)	5,361.57	2,568.00	2,793.57	52.10
+ Loss of Use (4.0 x S\$90.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,935.45		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 19/04/2021

Estimated Period of Repair: 4.0 days

 Inspected At: Hui Yang Motor Pte Ltd (HQ)
 176 Sin Ming Drive #04-02, Sin Ming AutoCare
 Singapore 575721
Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Bent	1,250.00 FL	*1,087.10 FL
2	1		*REAR LH DOOR PROTECTOR	Necessary	295.50 FL	*288.20 FL
3	1		*REAR LH DOOR PROTECTOR CHROME	Necessary	185.25 FL	*65.00 FL
4	12		*FRONT LH DOOR FRAME TOP MOULDING RIVET	Necessary	96.00 FL	*60.00 FL
5	1		*REAR LH DOOR INNER RUBBER	Serviceable	180.50 FL	*- FL
6	1		*LH SIDE SKIRT	Mtg Cracked	780.50 FL	*617.80 FL
7	1		*REAR LH SPORT RIM	Dented	600.00 FS	*280.00 FS
					Sub Total (\$)	3,387.75
					- List Item Discount on L Items 25.00/25.00% (\$)	696.94
					Total Parts (\$)	2,690.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT LH REAR DOOR GLASS	New	120.00	60.00
2	TUFFKOTE	New	80.00	30.00
3	WIRING	New	120.00	20.00
4	SPRAY PAINTING	New	1,000.00	600.00
5	LABOUR CHARGES	New	1,000.00	450.00
Gross Labour Cost (S\$)			2,320.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >