

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBG2382Z

Accident Date : 16/4/2021

Location : BEFORE JALAN BOON LAY AYE EXIT

Model:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(30/6/2017)

Acknowledged by Repairer

Signature (GREAT

AMERICAN)

JN1MC2E2K20007791

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Delint</i>	-	-	796.20
2	1 set	Rear bumper reverse sensor <i>Damaged</i>	-	280.00	-
3	10 pcs	Rear bumper clips <i>Nu</i>	-	30.00	-
4	1 pc	Rear tail-gate <i>Dented</i>	-	-	2,200.40
5	1 pc	Rear tail-gate weatherstrip <i>lit</i>	-	-	586.10
6	1 pc	Rear tail-gate 'NISSAN' emblem <i>Green</i>	-	-	86.70
7	1 pc	Rear tail-gate '70KM/PH' emblem	-	-	25.00
8	1 pc	Rear tail-gate company sticker <i>Nu</i>	-	300.00	-
9	1 pc	Rear tail-gate lock (upper) <i>Damaged</i>	-	-	268.40
10	1 pc	Rear tail-gate lock (lower) <i>Nu</i>	-	-	106.10
11	1 pc	Rear tail-gate chrome moulding <i>Cracked</i>	-	-	586.20
12	2 pcs	Rear tail-gate o/s & n/s rubber stopper <i>Nu</i>	-	-	40.00
13	2 pcs	Rear o/s & n/s tail-lamp <i>O/s cracked</i>	-	-	1,197.20
14	1 pc	Rear windscreen <i>Shattered</i>	-	-	1,120.00
15	1 pc	Rear windscreen sealant <i>Nu</i>	-	80.00	-
16	1 pc	Rear windscreen moulding <i>Nu</i>	-	60.00	-
17	1 pc	Rear solar film <i>Nu</i>	-	160.00	-
18	1 pc	Rear wiper motor <i>Damaged</i>	-	-	573.40
19	1 pc	Rear wiper assembly garnish <i>Nu</i>	-	-	80.00
20	1 pc	Rear wiper arm <i>Nu</i>	-	-	120.00
21	1 pc	Rear reverse mirror <i>Cracked</i>	-	-	232.00
22	1 pc	Rear reverse mirror garnish <i>Nu</i>	-	-	80.00
23	1 pc	Rear reg. no. plate <i>Green</i>	-	45.00	-
24	1 pc	Rear reg. no. plate bracket	-	29.00	-
25	2pcs	Rear reg. no. plate lamp <i>Nu</i>	-	-	166.00
26	1 pc	Rear tail-gate floor plywood <i>Nu</i>	-	450.00	-
Sub-Total:			0.00	1,434.00	8,263.70
			30%	0%	10%
After Less %:			0.00	1,434.00	7,437.33
Labour					
1		To dismantle rear portion, straighten & welding.	800.00	400	
2		To spray painting.	600.00	400	
3		To remove & refit rear windscreen.	160.00	120	
4		To remove & replace rear reverse sensor.	100.00	50	
5		To check wiring.	80.00	30	
6		To re-seal anti-rust.	80.00	40	
Sub-Total:				1,820.00	
Total:					10,691.33
After Less 20%:					8,553.06


690.
200 (SN)
1816.
228.
5640.10
385
Len 10% 5076.09
356
SN: 780
60 (SN)

Adrian C
1/2 19/04/21
03 Days
Total: 6896.09
1/2: 5.5K

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



8778 1999
24 hr accident call



GBG2382Z estimatePg1