



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Yamaha Aerox (FBQ4508M)
Date of Loss	29 March 2021
Time of Loss	10:40
Loss Description	SH6335C (INSD) HIT REAR OF FBQ4508M (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	-\$3,045.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details


Vehicle Registration#	FBQ4508M	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>05/10/2019</div> <div></div>
Mileage	<div>16215</div>	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2019</div>



Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
----------	------------------	-------------------------

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Yamaha	<input type="text" value="YAMAHA"/>
Model	Aerox	<input type="text" value="AEROX GDR155A CVT A"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MH3SG4640KJ057120"/>
Engine No		<input type="text" value="G3J8E0107693"/>
Engine Capacity		<input type="text" value="155"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	ONG CHIN KEONG SEBASTIAN	<input type="text" value=""/>
Date of Birth	9 December 1988	<input type="text" value="DD/MM/YYYY"/> 
Age	32	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	S8849639F	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

19/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

110/80-14

Front left side

DUNLOP5mm

Front right side

Spare wheel

Rear Tyre Size

140/70-14

Rear left side

DUNLOP5mm

Rear right side



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Service Requests

Messages











Claims













<< Assessment Details








General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		FRONT FORK	Twisted	0	350	No	0	10	0	0	315	R
	0	1		FRONT FORK GUARD	Cut	0	60	No	0	10	0	0	54	R
	0	1		FRONT UNDER BRACKET	Bent	0	110	No	0	10	0	0	99	R
	0	1		FRONT WHEEL	Cut	0	220	No	0	10	0	0	198	R
	0	1		FRONT BRAKE DISC	Bent	0	110	No	0	10	0	0	99	R
	0	1		FRONT ABS DISC	Serviceable	0	0	No	0	0	0	0	0	D
	0	1		FRONT WHEEL AXLE	Bent	0	45	No	0	10	0	0	40.5	R

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		FRONT HEAD LIGHT	Broken	0	220	No	0	10	0	0	198	Rd
	0	1		FRONT HEAD LIGHT STAY	Bent	0	85	No	0	10	0	0	76.5	Rd
	0	1		MIRROR RH	Cut	0	45	No	0	10	0	0	40.5	Rd
	0	1		FRONT MUDGUARD	Broken	0	65	No	0	10	0	0	58.5	Rd
	0	1		FRONT COWLING LH	Broken	0	110	No	0	10	0	0	99	Rd
	0	1		FRONT COWLING RH	Broken	0	110	No	0	10	0	0	99	Rd
	0	1		FRONT COWLING CENTER	Missing	0	65	No	0	10	0	0	58.5	Rd
	0	1		FRONT SIDE COVER INNER LH	Damaged	0	85	No	0	10	0	0	76.5	Rd
	0	1		FRONT SIDE COVER INNER RH	Damaged	0	85	No	0	10	0	0	76.5	Rd
	0	1		FRAME COVER LH	Serviceable	0	0	No	0	0	0	0	0	Dt

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		FRAME COVER RH	Serviceable	0	0	No	0	0	0	0	0	Dis
	0	1		FLOOR BOARD LH	Cut	0	68	No	0	10	0	0	61.2	Re
	0	1		FLOOR BOARD RH	Cut	0	68	No	0	10	0	0	61.2	Re
	0	1		UNDER COVER	Missing	0	85	No	0	10	0	0	76.5	Re
	0	1		UNDER COVER LH	Cut	0	70	No	0	10	0	0	63	Re
	0	1		UNDER COVER RH	Cut	0	70	No	0	10	0	0	63	Re
	0	1		FRONT SIGNAL RH	Cut	0	68	No	0	10	0	0	61.2	Re
	0	1		FRONT SIGNAL LH	Cut	0	68	No	0	10	0	0	61.2	Re
	0	1		FRONT MUDGUARD LH	Broken	0	40	No	0	10	0	0	36	Re
	0	1		SIDE COVER LH	Serviceable	0	0	No	0	0	0	0	0	Dis
	0	1		SIDE COVER RH	Cut	0	72	No	0	10	0	0	64.8	Re
	0	1		EXHAUST	Serviceable	0	0	No	0	0	0	0	0	Dis

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		EXHAUST COVER	Cut	0	65	No	0	10	0	0	58.5	Rd
	0	1		HANDLE	Bent	0	110	No	0	10	0	0	99	Rd
	0	1		HANDLE COVER FRONT	Cut	0	68	No	0	10	0	0	61.2	Rd
	0	1		HANDLE COVER REAR	Cut	0	68	No	0	10	0	0	61.2	Rd
	0	1		METER	Cut	0	220	No	0	10	0	0	198	Rd
	0	1		SEAT	Damaged	0	180	No	0	10	0	0	162	Rd
	0	1		CONE BEARING	Necessary	0	60	No	0	10	0	0	54	Rd







Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TOW	0	40	0	0	Reviewing		
	0		LABOUR	0	300	0	0	Reviewing		
	0		FRAME REPAIR	0	200	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 3 DAYS	Approve	0	0		

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$3,370.50
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,830.50
Labour	\$0.00	\$540.00

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	2700		

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,700.00
------------------------	--------	-----------------------	------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$2,700.00

Submit for Review