

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21004831/KBA3Q2  
**Date:** 12/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
<b>Claimant Vehicle No :</b>	SMQ4697U	<b>Insured Vehicle No :</b>	SLL7627R
Date of Loss:	11/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001680

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMQ4697U</b>		
Make & Model:	MERCEDES-BENZ GLC 200, 2.0 (A)	Engine No:	27492031880677
Reg. Date:	19/11/2019 (Man. Year: 2019)	Chassis No:	WDC2539422F672007
Colour:	Metallic Grey	Odometer:	15727 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,183.00	3,164.00	3,019.00	48.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	630.00	1,430.00	69.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,243.00</b>	<b>3,794.00</b>	<b>4,449.00</b>	<b>53.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	577.01	265.58	311.43	53.97

<b>Nett Amount (\$)</b>	<b>8,820.01</b>	<b>4,059.58</b>	<b>4,760.43</b>	<b>53.97</b>
		<hr/>		
<b>+ Loss of Use (4.0 x S\$150.00/day) (\$)</b>		600.00		
<b>+ Doc/Search Fee (\$)</b>		7.45		
		<hr/>		
<b>Nett Liability (\$)</b>		<b>4,667.03</b>		
		<hr/>		

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 16/04/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
 160 Sin Ming Drive, #07-01/06 Sin Ming Autocity  
 Singapore 575722

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2021)
<b>Parts:</b>	M1-SUV	MERCEDES-BENZ GLC 200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ4697U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Repair	1,600.00 FN	*- FN
2	1		*TAILLAMP ASSY -RH	Serviceable	565.00 FN	*- FN
3	1		*REAR BUMPER (UPPER)	Buckled	1,690.00 FN	*960.00 FN
4	1		*REAR BUMPER (LOWER)	Dented	558.00 FN	*558.00 FN
5	1		*REAR BUMPER REINFORCEMENT	Bent	812.00 FN	*812.00 FN
6	1		*REAR BUMPER REFLECTOR -RH	Scratched	33.00 FN	*33.00 FN
7	2		*REAR BUMPER REVERSE SENSOR	Serviceable	380.00 FN	*- FN
8	6		*REAR BUMPER SENSOR SEALS	Necessary	72.00 FN	*72.00 FN
9	1		*REAR BUMPER LOWER CHROME	Cracked	510.00 FN	*510.00 FN
10	1		*REAR BUMPER TOW COVER	Dented	65.00 FN	*65.00 FN
11	1		*REAR BUMPER CLIPS (15 PCS)	Necessary	121.50 FS	*50.00 FS
12	1		*REAR EXHAUST END CHROME -RH	Dented	450.00 FN	*450.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,856.50</b>	<b>3,510.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	673.50	346.00
<b>Total Parts (\$\$)</b>	<b>6,183.00</b>	<b>3,164.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REFIX REAR BUMPER SENSOR	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL REAR CHASSIS FRAME ,TO CUT AND WELD REAR END PANEL ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT ADJUST THE SAME	New	1,000.00	300.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	250.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,060.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >