

ASS. REC. BY:

REF:

TII / 21004831116
GRB

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Tony Luck

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA 4697U Yr Regn: 11.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Mer GLC200 c.c. 1991Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 15727 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC 25394221-672007Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 11/4/21

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/5 \$3794.00 Cash

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Fees

Others

TOTAL



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

ATTN : ACCOUNTS DEPT

FAX : *Not Authorized*

Recovery B4 pain

YOUR REF NO : SLL7627R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : INDIA INTERNATIONAL INSURANCE PTE LTD

ACCIDENT DATE : 11/04/2021

TP VEH REG NO : SLL7627R

16/4/2021 3 days

19/4/2021

ESTIMATE

NO : QUOT202104-000028(00)

DATE : 15/04/2021

POLICY NO : 999995580

VEH REG NO : SMQ4697U

MAKE/MODEL : MERCEDES BENZ GLC200
(R18 LED)

CHASSIS NO : WDC2539422F672007

ENGINE NO : 27492031880677

REG. DATE : 2019

\$ 3794.00

Estimate Repair Cost to Vehicle No : SMQ4697U

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear end panel	1	1,600.00	1,600.00 X
2 Taillamp-assy - RH	1	565.00	565.00 X
3 Rear bumper (upper) → 960	1	1,690.00	1,690.00 ✓
4 Rear bumper (lower)	1	558.00	558.00 ✓
5 Rear bumper reinforcement → 812	1	812.00	812.00 ✓
6 Rear bumper reflector - RH	1	33.00	33.00 ✓
7 Rear bumper-reverse sensor	2	190.00	380.00 X
8 Rear bumper sensor seals	6	12.00	72.00 ✓
9 Rear bumper lower chrome -10% \$ 4,190.00	1	510.00	510.00 ✓
10 Rear bumper tow cover	1	65.00	65.00 ✓
11 Rear bumper clips	15	9.00	135.00 ✓
12 Rear exhaust end chrome - RH → \$ 3,771.00	1	450.00	450.00 ✓
			6,870.00
		Less 10%	687.00
			6,183.00
LABOUR			
13 To remove and refix rear bumper sensor	1	100.00	100.00 601
14 To check and rectify wiring system	1	80.00	80.00 201
15 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit adjust the same.	1	1,000.00	1,000.00 3001
16 To putty and spray paint on affected areas	1	800.00	800.00 2501
17 To apply rust-proofing on replaced and repaired panels	1	80.00	80.00 X
			2,060.00
		TOTAL	S\$ 8,243.00
		ADD GST @ 7%	577.01
		GRAND TOTAL	S\$ 8,820.01

SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED TWENTY AND CENTS ONE ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLL7627R
CLAIM TYPE : THIRD PARTY
TP INS. CO. : INDIA INTERNATIONAL INSURANCE PTE LTD
ACCIDENT DATE : 11/04/2021
TP VEH REG NO : SLL7627R

ESTIMATE

NO : QUOT202104-000028(00)
DATE : 15/04/2021
POLICY NO : 999995580
VEH REG NO : SMQ4697U
MAKE/MODEL : MERCEDES BENZ GLC200
(R18 LED)
CHASSIS NO : WDC2539422F672007
ENGINE NO : 27492031880677
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMQ4697U

Description	Quantity	Unit Price	Amount
		S\$	S\$

4,451.00
7% 311.57
4,762.57

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE