

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/CTI21004832/UEA3Q2
Date: 17/05/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00113302000
Claimant Vehicle No :	FBN1783U	Insured Vehicle No :	GBJ780E
Date of Loss:	09/04/2021	Nature of Claim:	TP
			Claim No: SNM21D202070/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1783U		
Make & Model:	YAMAHA NMAX155, 155cc ABS CVT	Engine No:	G3H6E0009673
Reg. Date:	25/07/2018 (Man. Year: 2018)	Chassis No:	MH3SG431000007476
Colour:	White	Odometer:	71698 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110-70-13	Rear Tyre Size:	130-70-13
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,552.00	933.30	618.70	39.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	791.00	515.00	276.00	34.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,343.00	1,448.30	894.70	38.19
+ GST 7.00/7.00% (S\$)	164.01	101.38	62.63	38.19

Nett Amount (S\$)**2,507.01****1,549.68****957.33****38.19**INSPECTION

Date of Assignment: 22/04/2021

Date Inspected: 16/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 May 2021)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1783U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	34.00 F	*34.00 FL
2	1		*BOARD FOOTREST LH	Cut	53.00 F	*53.00 FL
3	1		*BOX FILTER AIR OUTER FRONT	Cut	11.00 F	*11.00 FL
4	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	222.00 F	*222.00 FL
5	1		*COVER CLUTCH OUTER	Cut	28.00 F	*28.00 FL
6	1		*COVER SIDE CENTRE LH (WHITE)	Cut	22.00 F	*22.00 FL
7	1		*COVER SIDE LH (SILVER)	Cut	38.00 F	*38.00 FL
8	1		*COWLING FRONT LH (WHITE)	Cut	33.00 F	*33.00 FL
9	1		*ENGINE BRACKET COMP	Bent	70.00 F	*70.00 FL
10	1		*LAMP SIGNAL FRONT LH	Cut	35.00 F	*35.00 FL
11	1		*LEVER BRAKE LH	Cut	18.00 F	*18.00 FL
12	1		*MIRROR LH	Cut	37.00 F	*37.00 FL
13	1		*MUDGUARD FRONT (WHITE)	Cut	47.00 F	*47.00 FL
14	1		*MUDGUARD REAR	Deformed	47.00 F	*47.00 FL
15	1		*PANEL 1 (SILVER) LH	Cut	22.00 F	*22.00 FL
16	1		*PIPE EXHAUST ASSY	Repair	407.00 F	*- FL
17	1		*METER IU (12V) NEW MODEL	Cut	289.00 FS	*165.00 FS
18	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	28.00 FS	*12.00 FS
19	1		*STICKER (CISCO) COVER CENTRE LH	Necessary	37.00 FS	*37.00 FS
20	1		*STICKER (CISCO) COWLING FRONT LH	Necessary	37.00 FS	*37.00 FS
21	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	37.00 FS	*37.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,552.00	1,005.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	71.70
Total Parts (\$)	1,552.00	933.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	504.00	300.00
2	SPRAY LACQUER ON FRONT COWLING LH	New	91.00	70.00
3	SPRAY LACQUER ON FRONT MUDGUARD	New	49.00	40.00
4	SPRAY LACQUER ON SIDE COVER LH	New	91.00	70.00
5	TRANSPORT CHARGES	New	56.00	35.00
Gross Labour Cost (S\$)			791.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >