



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288X
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 38085

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

VEHICLE NO. : FBN1783U
MAKE/MODEL : YAM / NMAX155 ABS

DATE : 13/04/2021
CLAIM NO. : 11707
POLICY NO. : MC/00833874
FROM : HASRIANAH

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	CUY 34.00 ✓
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00	CUY 53.00 ✓
3	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	CUY 11.00 ✓
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00	CUY 222.00 ✓
5	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	CUY 28.00 ✓
6	COVER SIDE CENTRE LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	CUY 22.00 ✓
7	COVER SIDE LH (SILVER) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	CUY 38.00 ✓
8	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	CUY 33.00 ✓
9	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	CUY 70.00 ✓

*38085 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-4-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install ☒	8.00	\$63.00	300 504.00
11	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	CU? 35.00
12	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	CU? 18.00
13	METER IU (12V) NEW MODEL P/N: 34351 - (REPORTED BY MECHANIC)	REPLACE ☒	1.00	\$289.00	CU? 289.00 165 s.n
14	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	CU? 37.00
15	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	CU? 47.00
16	MUDGUARD REAR P/N: 63129 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	De 47.00
17	PANEL 1 (SILVER) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	CU? 22.00
18	PIPE EXHAUST ASSY P/N: 58083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$407.00	n 407.00 X s.n
19	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE ☒	1.00	\$28.00	Self 28.00 12
20	SPRAY LACQUER ON FRONT COWLING LH - (REPORTED BY MECHANIC)	Spray ☒	1.00	\$91.00	70 91.00
21	SPRAY LACQUER ON FRONT MUDGUARD - (REPORTED BY MECHANIC)	Spray ☒	1.00	\$49.00	40 49.00
22	SPRAY LACQUER ON SIDE COVER LH - (REPORTED BY MECHANIC)	Spray ☒	1.00	\$91.00	70 91.00
23	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE ☒	1.00	\$37.00	n 37.00 s.n
24	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE ☒	1.00	\$37.00	n 37.00 s.n

*38085 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	.STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
26	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	*	1.00	\$56.00	56.00

SUB TOTAL	\$2,343.00
GST @ 7 %	\$164.01
GRAND TOTAL (SGD)	\$2,507.01

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Let Auto Consultants hence notify the Repairs of the following:

- To notify before spray painting
- To notify before parts during resurvey
- Parts price are subject to confirmation
- This quote is given on a "Without Prejudice" basis
- To notify before work is allowed
- Supplementary (works) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-717
10%
645.3
1448.30

*38085 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 38085

- Rev. 1

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534

DATE : 13/04/2021
CLAIM NO. : 11707
POLICY NO. : MC/00833874

ATTN: CHINA TAIPING INSURANCE (S) PTE LTD

FROM : HASRIANAH

VEHICLE NO. : FBN1783U
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$53.00 Disc %: 10.00	47.70
3	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00 Disc %: 10.00	9.90
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$222.00 Disc %: 10.00	199.80
5	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
6	COVER SIDE CENTRE LH (WHITE) P/N: 58097 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
7	COVER SIDE LH (SILVER) P/N: 60877 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
8	COWLING FRONT LH (WHITE) P/N: 58179 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00 Disc %: 10.00	29.70
9	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00 Disc %: 10.00	63.00

*38085 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2003-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
10	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$300.00	300.00
11	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
12	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
13	METER IU (12V) NEW MODEL P/N: 34351 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$165.00	165.00
14	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00 Disc %: 10.00	33.30
15	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00 Disc %: 10.00	42.30
16	MUDGUARD REAR P/N: 63129 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00 Disc %: 10.00	42.30
17	PANEL 1 (SILVER) LH P/N: 60905 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00 Disc %: 10.00	19.80
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
19	SPRAY LACQUER ON FRONT COWLING LH - (REPORTED BY MECHANIC)	Spray	1.00	\$70.00	70.00
20	SPRAY LACQUER ON FRONT MUDGUARD - (REPORTED BY MECHANIC)	Spray	1.00	\$40.00	40.00
21	SPRAY LACQUER ON SIDE COVER LH - (REPORTED BY MECHANIC)	Spray	1.00	\$70.00	70.00
22	STICKER (CISCO) COVER CENTRE LH P/N: 58614 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
23	STICKER (CISCO) COWLING FRONT LH P/N: 58616 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
24	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00

*38085 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$35.00	35.00
SUB TOTAL					\$1,448.30
GST @ 7 %					\$101.38
GRAND TOTAL (SGD)					\$1,549.68

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38085 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-4-0363
ISO 9001:2015