

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21004833/KRA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100401665
<b>Claimant Vehicle No :</b>	SFR3111C	<b>Insured Vehicle No :</b>	SKR4878H
Date of Loss:	14/04/2021	Nature of Claim:	TP
		Claim No:	6073823977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFR3111C</b>	Engine No:	1ZZ3222925
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W003001649
Reg. Date:	16/01/2009 (Man. Year: 2008)	Odometer:	212563 km
Colour:	Metallic Pearl White		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,887.65	4,100.92	786.73	16.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,590.00	980.00	38.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,457.65</b>	<b>5,690.92</b>	<b>1,766.73</b>	<b>23.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,550.00</b>		
<b>(S\$)</b>	7,457.65	4,550.00	2,907.65	38.99
<b>+ GST 7.00/7.00% (S\$)</b>	522.04	318.50	203.54	38.99
<b>Nett Amount (S\$)</b>	<b>7,979.69</b>	<b>4,868.50</b>	<b>3,111.19</b>	<b>38.99</b>
<b>+ Car Rental (7.0 x S\$120.00/day) (S\$)</b>		840.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,710.50</b>		

INSPECTION

Date of Assignment:	16/04/2021	
Date Inspected:	19/04/2021	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,210.40 FL	*1,210.40 FL
2	1		*TAIL GATE INNER LOCK	Dented	443.50 FL	*388.80 FL
3	1		*TAIL GATE RUBBER (50%)	Cut	228.08 FS	*152.05 FS
4	1		*TAIL GATE INNER TRIM	Mtg Cracked	328.20 FL	*328.20 FL
5	1		*TAIL GATE GLASS MOULDING	Necessary	93.40 FL	*93.40 FL
6	1		*TAIL GATE OUTER CHROME	Cracked	239.10 FL	*239.10 FL
7	1		*TAIL GATE LOGO	Necessary	50.20 FL	*50.20 FL
8	2		*TAILLAMP	Cracked	945.20 FL	*945.20 FL
9	1		*REAR END PANEL -OUTER	Bent	590.60 FL	*566.10 FL
10	1		*REAR END PANEL -INNER	Bent	199.60 FL	*199.60 FL
11	1		*END PANEL TOP GARNISH	Mtg Cracked	232.90 FL	*232.90 FL
12	1		*REAR BUMPER FASCIA	Buckled	470.70 FL	*470.70 FL
13	2		*REAR BUMPER BRACKET	Distorted	96.80 FL	*96.80 FL
14	1		*REAR BUMPER SIDE RETAINER	N/S Distorted	114.20 FL	*57.10 FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	108.20 FL	*- FL
16	1		*REAR FLOOR PANEL	Repair	543.10 FL	*- FL
17	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
18	1		*SET REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$\$)	6,304.18 5,320.55
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,416.53 1,219.63
					Total Parts (\$\$)	4,887.65 4,100.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	100.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	1,200.00	750.00
5	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	600.00
<b>Gross Labour Cost (\$)</b>			<b>2,570.00</b>	<b>1,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >