

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004835/GPA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900232720
Claimant Vehicle No :	SME6946B	Insured Vehicle No :	SMQ1699J
Date of Loss:	13/04/2021	Nature of Claim:	TP
		Claim No:	0286112016SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6946B	Engine No:	PE21188891
Make & Model:	MAZDA 6, 2.0 SEDAN STANDARD 2WD (A)	Chassis No:	JM6GL1072K0304285
Reg. Date:	11/10/2018 (Man. Year: 2018)	Odometer:	68304 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,037.68	1,670.96	15,366.72	90.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,020.00	440.00	4,580.00	91.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,057.68	2,110.96	19,946.72	90.43
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	22,057.68	1,700.00	20,357.68	92.29
+ GST 7.00/7.00% (S\$)	1,544.04	119.00	1,425.04	92.29
Nett Amount (S\$)	23,601.72	1,819.00	21,782.72	92.29
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,055.45		

INSPECTION

Date of Assignment:	16/04/2021	RICO 60 AUTO SERVICES PTE LTD (HQ)
Date Inspected:	19/04/2021 Inspected At:	8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Estimated Period of Repair:	2.0 days	Singapore 415875

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	1,215.80 FL	*- FL
2	1		*BOOT LID EMBLEM	Not Necessary	108.90 FL	*- FL
3	1		*BOOT LID EMBLEM (MAZDA 6)	Not Necessary	94.70 FL	*- FL
4	1		*BOOT LID EMBLEM (SKYACTIVE)	Not Necessary	87.50 FL	*- FL
5	2		*BOOT LID LAMP	Not Necessary	1,592.60 FL	*- FL
6	1		*BOOT LID CENTER CHROME	Not Necessary	452.50 FL	*- FL
7	2		*BOOT LID CAR PLATE LAMP	Not Necessary	178.00 FL	*- FL
8	1		*BOOT LID CAR PLATE LAMP GARNISH	Not Necessary	112.00 FL	*- FL
9	1		*BOOT LID OPENER HANDLE	Not Necessary	177.80 FL	*- FL
10	2		*BOOT LID STOPPER	Not Necessary	36.20 FL	*- FL
11	1		*BOOT LID LOCK ASSY	Not Necessary	280.40 FL	*- FL
12	1		*BOOT LID LOCK CATCH	Not Necessary	56.20 FL	*- FL
13	1		*BOOT LID WEATHERSTRIP	Not Necessary	172.80 FL	*- FL
14	1		*BOOT LID DETECTOR	Not Necessary	277.00 FL	*- FL
15	1		*TAILLAMP	Not Necessary	3,058.00 FL	*- FL
16	1		*TAILLAMP PANEL LH	Not Necessary	254.00 FL	*- FL
17	1		*REAR BUMPER	Broken	1,266.90 FL	*1,099.00 FL
18	1		*REAR BUMPER SIDE RETAINER	N/S Broken / O/S Not Necessary	159.60 FL	*30.00 FL
19	1		*REAR BUMPER REFLECTOR	N/S Broken / O/S Not Necessary	308.60 FL	*48.00 FL
20	3		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,053.00 FL	*361.80 FL
21	2		*REAR BUMPER TOWING COVER	Not Necessary	116.60 FL	*- FL
22	1		*REAR BUMPER CENTER BRACKET	Not Necessary	19.80 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	588.30 FL	*423.10 FL
24	2		*REAR BUMPER SIDE COVER	Not Necessary	144.60 FL	*- FL
25	1		*REAR END PANEL	Not Necessary	788.90 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.10 FL	*- FL
27	1		*REAR FLOOR PANEL	Not Necessary	1,086.90 FL	*- FL
28	1		*REAR FLOOR PANEL TOP SPONGE	Cracked	477.90 FL	*89.30 FL
29	1		*REAR FLOOR PANEL TOP SIDE TOOL BOX	Not Necessary	179.00 FL	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	498.00 FL	*- FL
31	1		*REAR FENDER LH	Not Necessary	1,057.00 FL	*- FL
32	1		*REAR FENDER INNER TRIM LH	Not Necessary	544.60 FL	*- FL
33	1		*REAR FENDER INNER COWLING LH	Not Necessary	159.00 FL	*- FL
34	1		*REAR FENDER QUARTER GARNISH	Not Necessary	185.00 FL	*- FL
35	1		*REAR FENDER AIRVENT	Not Necessary	54.00 FL	*- FL
36	1		*REAR DOOR OUTER STRIP	Not Necessary	325.00 FL	*- FL
37	1		*REAR EXHAUST SILENCER	Not Necessary	1,745.00 FL	*- FL
38	2		*REAR EXHAUST MOUNTING	Not Necessary	38.40 FL	*- FL
39	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	254.00 FL	*- FL
40	1		*REAR BUMPER PLATE	Not Necessary	80.00 FS	*- FS
41	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
42	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
43	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
45	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*REAR FENDER INNER COWLING CLIP	Not Necessary	40.00 FS	*- FS
47	1		*SET REAR FENDER INNER TRIM RH CLIP	Not Necessary	50.00 FS	*- FS
48	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
50	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
51	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **20,914.60** **2,081.20**
- List Item Discount on L Items 20.00/20.00% (\$) 3,876.92 410.24

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						17,037.68
						1,670.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	200.00
3	APPLY TUFF COATING TREATMENT	New	300.00	0.00
4	DISMANTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	150.00	0.00
5	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS PERFORM DISTANCE SENSORY TESTING	New	100.00	40.00
6	DISAMANTLE AND INSTALL REAR SEATS ,SPEAKER BOARD AND SEATS TRIMMING	New	350.00	0.00
7	REMOVE AND INSTALL REAR WINDSCREEN	New	200.00	0.00
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	100.00	0.00
9	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY ,PERFORM AIMING AND ADJUST TO POSITION	New	120.00	0.00
10	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	150.00	0.00
11	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY REALIGN TO POSITION	New	150.00	0.00
Gross Labour Cost (\$\$)			5,020.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >