

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004836/GRA3Q2
Date: 10/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900232720
Claimant Vehicle No :	SMR5051X	Insured Vehicle No :	SMQ1699J
Date of Loss:	13/04/2021	Nature of Claim:	TP
		Claim No:	0286112016SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR5051X		
Make & Model:	AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)	Engine No:	CZC202373
Reg. Date:	28/10/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ8V0F1024414
Colour:	Black	Odometer:	116743 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,369.87	13,504.25	22,865.62	62.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	2,990.00	3,010.00	50.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,369.87	16,494.25	25,875.62	61.07
Approved Total (Overridden) (S\$)		13,200.00		

(S\$)	42,369.87	13,200.00	29,169.87	68.85
+ GST 7.00/7.00% (S\$)	2,965.89	924.00	2,041.89	68.85
Nett Amount (S\$)	45,335.76	14,124.00	31,211.76	68.85
+ Car Rental (12.0 x S\$120.00/day) (S\$)		1,440.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		15,571.45		

INSPECTION

Date of Assignment: 16/04/2021

Date Inspected: 19/04/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	2,333.40 FL	*1,564.00 FL
2	1		*BOOT LID LOGO	Not Necessary	96.00 FL	*- FL
3	2		*BOOT LID CAR PLATE LAMP	Cracked	190.00 FL	*113.00 FL
4	2		*BOOT LID LAMP	Cracked	1,754.80 FL	*425.00 FL
5	1		*BOOT LID INNER LOCK	Bent	552.00 FL	*225.00 FL
6	1		*BOOT LID LOCK CATCH	Not Necessary	66.00 FL	*- FL
7	1		*BOOT LID WEATHERSTRIP	Twisted	217.90 FL	*175.20 FL
8	2		*BOOT LID STOPPER	Distorted (1 PCS ONLY)	120.00 FL	*28.00 FL
9	1		*BOOT LID INNER TRIM	Cut	487.00 FL	*290.00 FL
10	2		*BOOT LID SIDE STOPPER	Not Necessary	180.00 FL	*- FL
11	2		*BOOT LID HINGE	Bent (1 PCS ONLY)	510.00 FL	*255.00 FL
12	1		*BOOT LID OUTER OPENER SWITCH	Damaged	159.00 FL	*67.00 FL
13	1		*REVERSE CAMERA	Not Necessary	995.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	1,900.40 FL	*1,325.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Cracked (1 PCS ONLY)	228.00 FL	*75.00 FL
16	1		*REAR BUMPER CENTER RETAINER	Cracked	298.00 FL	*147.50 FL
17	2		*REAR BUMPER LOWER BRACKET	Broken (1 PCS ONLY)	112.40 FL	*56.20 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	791.00 FL	*455.00 FL
19	1		*REAR BUMPER TOWING COVER	Broken	39.60 FL	*39.60 FL
20	4		*REAR BUMPER SENSOR	Damaged (3 PCS ONLY)	1,256.00 FL	*589.20 FL
21	1		*REAR BUMPER SENSOR WIREHARNESS	Broken	698.00 FL	*438.90 FL
22	4		*REAR BUMPER SENSOR HOLDER	Necessary (3 PCS ONLY)	124.80 FL	*54.00 FL
23	1		*REAR BUMPER LOWER GARNISH (CENTER)	Missing	195.00 FL	*168.00 FL
24	2		*REAR BUMPER REFLECTOR	Cracked (1 PCS ONLY)	356.00 FL	*21.20 FL
25	1		*REAR BUMPER LOWER DIFFUSER S3	Cut	932.00 FL	*495.00 FL
26	2		*TAIL LAMP	Cracked	1,899.40 FL	*1,516.00 FL
27	2		*TAIL LAMP SIDE GARNISH	Cracked	250.00 FL	*60.00 FL
28	1		*TAIL LAMP PANEL RH	Buckled	126.80 FL	*126.80 FL
29	1		*TAIL LAMP RAILING PANEL RH	Repair	143.20 FL	*- FL
30	1		*END PANEL	Buckled	1,234.90 FL	*660.00 FL
31	1		*END PANEL TOP GARNISH	Deformed	346.00 FL	*153.00 FL
32	1		*REAR AIR VENT RH	Deformed	97.40 FL	*33.00 FL
33	1		*REAR FLOOR PANEL	Repair	2,223.50 FL	*- FL
34	1		*REAR FLOOR SIDE PANEL RH	Repair	410.00 FL	*- FL
35	1		*REAR FLOOR TOP TOOL SPONGE	Cracked	372.20 FL	*199.89 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FLOOR TOP BOARD	Cracked	689.00 FL	*180.50 FL
37	1		*REAR FENDER RH	Buckled	2,330.80 FL	*1,844.00 FL
38	1		*REAR FENDER GLASS WITH MOULDING RH	Not Necessary	765.30 FL	*- FL
39	1		*REAR FENDER WHEEL HOUSING RH	Repair	972.50 FL	*- FL
40	1		*REAR FENDER INNER TRIM	N/S Not Necessary / O/SCracked	1,304.00 FL	*652.00 FL
41	1		*REAR FENDER INNER SHIELD RH	Deformed	219.00 FL	*177.25 FL
42	1		*FUEL LID COVER	Not Necessary	112.50 FL	*- FL
43	1		*FUEL LID COVER LOCK COVER	Not Working	267.40 FL	*81.00 FL
44	1		*REAR EXHAUST PIPE	Bent	1,689.00 FL	*712.00 FL
45	2		*REAR EXHAUST MOUNTING	Bent (1 PCS ONLY)	120.00 FL	*60.00 FL
46	1		*REAR EXHAUST PIPE BRACKET	Not Necessary	98.00 FL	*- FL
47	1		*REAR EXHAUST HEAT PLATE	Not Necessary	277.00 FL	*- FL
48	1		*REAR DOOR RH	Repair	1,624.00 FL	*- FL
49	1		*REAR DOOR FRAME TOP RUBBER RH	Not Necessary	279.80 FL	*- FL
50	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	198.00 FL	*- FL
51	1		*REAR DOOR INNER LOCK RH	Bent	452.40 FL	*289.60 FL
52	1		*REAR DOOR LOCK CATCH RH	Not Necessary	56.00 FL	*- FL
53	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	254.20 FL	*- FL
54	1		*REAR DOOR INNER TRIM RH	Not Necessary	890.00 FL	*- FL
55	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
56	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
57	1		*TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
58	1		*TAIL LAMP PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
59	1		*SET TAIL LAMP STICKER	Necessary	400.00 FS	*20.00 FS
60	1		*TAIL LAMP RAILING PANEL SEALANT	Not Necessary	80.00 FS	*- FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
62	1		*REAR WINDSCREEN INNER SEALANT	Necessary	60.00 FS	*20.00 FS
63	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
64	1		*REAR FENDER GLASS SEALANT	Necessary	80.00 FS	*20.00 FS
65	1		*REAR FENDER GLASS INNER SEAL	Necessary	60.00 FS	*10.00 FS
66	1		*REAR FENDER WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
68	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
69	1		*REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
70	1		*REAR BUMPER DIFFUSER CLIP	Necessary	40.00 FS	*20.00 FS
71	1		*SET REAR BUMPER SIDE SPOILER	Necessary	700.00 FS	*200.00 FS
72	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
73	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
74	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS
75	1		*REAR FLOOR SIDE PANEL SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*REAR FLOOR TOOLS BOX SEALANT	Not Necessary	150.00 FS	* - FS
77	4		*REAR EXHAUST CHROME HEAD	Not Necessary	1,000.00 FS	* - FS
78	1		*REAR DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	* - FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	38,084.60	14,191.84
- List Item Discount on L Items 5.00/5.00% (S\$)	1,714.73	687.59
Total Parts (S\$)	36,369.87	13,504.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	200.00	60.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX REAR WINDSCREEN	New	200.00	120.00
7	REMOVE AND REFIX REAR DOOR PART	New	150.00	60.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	40.00
9	TRANSFER BOOTLID MECHANISM	New	150.00	40.00
10	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	350.00	60.00
12	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	600.00	0.00
Gross Labour Cost (S\$)			6,000.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >