

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004843/ATCE2

**Date:** 08/09/2021

### REFERENCE

Insured/Claimant:	CHUA YONG KIAT	Policy No:	2070149988		
Date of Loss:	15/04/2021	Nature of Claim:	OD	Claim No:	1728998996SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW952C	Engine No:	DAX060695
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZF5L2007112
Reg. Date:	30/10/2020 (Man. Year: 2019)	Odometer:	9978 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$215,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,685.00	24,149.52	29,535.48	55.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,524.00	9,907.00	8,617.00	46.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>72,209.00</b>	<b>34,056.52</b>	<b>38,152.48</b>	<b>52.84</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>71,209.00</b>	<b>33,056.52</b>	<b>38,152.48</b>	<b>53.58</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>4,984.63</b>	<b>2,313.96</b>	<b>2,670.67</b>	<b>53.58</b>
<b>Nett Amount (S\$)</b>	<b>76,193.63</b>	<b>35,370.48</b>	<b>40,823.15</b>	<b>53.58</b>

### INSPECTION

Date of Assignment:	19/04/2021		
Date Inspected:	16/04/2021	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	12.0 days		

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,724.00 FS	*2,342.80 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	205.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	O/S Cracked	226.00 FS	*90.00 FS
5	1		*FRONT BUMPER GRILLE - CENTER LOWER	Cracked	144.00 FS	*114.80 FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	763.00 FS	*- FS
7	1		*FRONT BUMPER UNDERRUN BAR	Cut	518.00 FS	*414.00 FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	173.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	3,530.00 FS	*2,824.00 FS
10	1		*QUATTRO INSCRIPTION	Necessary	106.00 FS	*84.80 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
12	1		*FRONT BUMPER AIR GRILLE - LH / RH	O/S Cut	1,162.00 FS	*464.40 FS
13	2		*FRONT BUMPER GRILLE END CAP - LH / RH	Not Necessary	184.00 FS	*- FS
14	4		*FRONT BUMPER LOCKING CLIP	Not Necessary	16.00 FS	*- FS
15	1		*FRONT BUMPER FOAM - INNER	Deformed	177.00 FS	*141.60 FS
16	1		*FRONT REINFORCEMENT BEAM	Bent	981.00 FS	*784.40 FS
17	1		*FRONT BUMPER GUIDE - LH / RH	O/S Cracked	78.00 FS	*30.48 FS
18	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Bent	512.00 FS	*409.60 FS
19	1		*FRONT BUMPER TOP COVER	Cracked	129.00 FS	*102.80 FS
20	1		*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
21	1		*STICKER FOR AIR CONDITIONER	Necessary	20.00 FS	*15.52 FS
22	1		*WARNING SIGN FOR PEDESTRIAN PROTECTION	Not Necessary	30.00 FS	*- FS
23	4		*FRONT BUMPER PARKING AID SENSOR	Damaged	960.00 FS	*195.12 FS
24	4		*FRONT BUMPER SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
25	1		*WIRIG SET FOR FRONT BUMPER	Not Necessary	409.00 FS	*- FS
26	2		*HORN - LH / RH	Not Necessary	390.00 FS	*- FS
27	2		*FRONT FENDER - LH / RH	Repair	2,854.00 FS	*- FS
28	1		*FRONT FENDER BRACE - LH / RH	O/S Bent	450.00 FS	*179.60 FS
29	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	36.00 FS	*- FS
30	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	556.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	38.00 FS	*- FS
32	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	324.00 FS	*- FS
33	2		*FRONT WHEEL ARCH TRIM - LH / RH	Necessary	1,264.00 FS	*1,011.20 FS
34	1		*BONNET	Dented	4,058.00 FS	*3,246.40 FS
35	2		*BONNET HINGE - LH / RH	Not Necessary	322.00 FS	*- FS
36	1		*BONNET ATTACHEMENT PARTS	Not Necessary	141.00 FS	*- FS
37	1		*BONNET LOCK STRIKER - LH / RH	O/S Bent	240.00 FS	*96.00 FS
38	1		*BONNET SOUND ABSORBER	Not Necessary	317.00 FS	*- FS
39	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	56.00 FS	*43.84 FS
40	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	28.00 FS	*21.84 FS
41	1		*PLENUM CHAMBER COVER	Not Necessary	145.00 FS	*- FS
42	2		*BONNET LOCK	Not Necessary	427.00 FS	*- FS
43	1		*BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
44	1		*BONNET RELEASE ELEMENT	Not Necessary	58.00 FS	*- FS
45	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
46	1		*BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
47	1		*BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
48	1		*HEADLIGHT MOUNTING - LH / RH	O/S Cracked	236.00 FS	*94.40 FS
49	1		*LED HEADLIGHT - LH / RH	O/S Cracked	16,382.00 FS	*6,552.80 FS
50	2		*HEADLIGHT WASHER CYLINDER - LH / RH	Not Necessary	280.00 FS	*- FS
51	1		*HEADLIGHT WASHER HOSE	Not Necessary	125.00 FS	*- FS
52	1		*FRONT LOCK CARRIER	Cracked	1,400.00 FS	*1,120.00 FS
53	2		*FRONT LOCK CARRIER BRACE - LOWER LH / RH	Not Necessary	114.00 FS	*- FS
54	2		*RADIATOR SUPPORT - LOWER LH / RH	Not Necessary	106.00 FS	*- FS
55	1		*A/C CONDENSER	Dented	601.00 FS	*480.80 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	2		*A/C CONDENSER SEAL RING	Not Necessary	17.00 FS	*- FS
57	1		*OUTER TEMP SENSOR BRACKET	Damaged	16.00 FS	*12.72 FS
58	1		*CHARGE AIR COOLER	Dented	819.00 FS	*654.80 FS
59	1		*RADIATOR	Bent	919.00 FS	*735.20 FS
60	1		*COOLANT	Necessary	269.00 FS	*214.56 FS
61	1		*FAN RING	Not Necessary	430.00 FS	*- FS
62	1		*RADIATOR FAN WITH CONTROL UNIT	Not Necessary	2,394.00 FS	*- FS
63	1		*RADIATOR LOUVRE	Damaged	534.00 FS	*427.20 FS
64	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	48.00 FS	*- FS
65	1		*RADIATOR AIR GUIDE - CENTER	Deformed	42.00 FS	*33.28 FS
66	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	48.00 FS	*- FS
67	2		*RADIATOR AIR GUIDE - LH / RH	Deformed	116.00 FS	*92.64 FS
68	1		*CAMSHAFT MAGNET COVER	Not Necessary	240.00 FS	*- FS
69	1		*S-LINE INSCRIPTION	O/S Necessary	255.00 FS	*102.00 FS
70	1		*FRONT DOOR WINDOW SLOT SEAL - LH / RH	N/S Cut	1,232.00 FS	*492.40 FS
71	1		*ENGINE OIL	Necessary	180.00 FS	*144.00 FS
72	2		*CAMSHAFT MAGNET	Not Necessary	338.00 FS	*- FS
73	2		*CONNECTOR FOR MAGNET	Not Necessary	302.00 FS	*- FS
74	1		*MAGNET COVER END CAP	Cracked	31.00 FS	*24.64 FS
75	1		*INTAKE AIR DUCT	Not Necessary	84.00 FS	*- FS
76	1		*INTAKE AIR HOSE	Not Necessary	95.00 FS	*- FS
77	1		*FRONT NUMBER PLATE	Dented	60.00 FS	*60.00 FS
78	1		*SUNDRIES	Necessary	400.00 FS	*89.20 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>53,685.00</b>	<b>24,149.52</b>
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULES	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGES AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH SIDE MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	800.00	560.00
5	TO RENEW ENGINE MAGNET COVER AND OTHER ENGINE COMPONENTS	New	480.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION . RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	2,500.00
7	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, BOTH FRONT FENDERS, BONNET, BONNET HINGES, BOTH FRONT WHEEL ARCH TRIMS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS	New	7,500.00	4,525.00
8	TO RECOVER AND TOW BACK VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
9	TO CARRY OUT PRE-DIAGNOSTIC AND POST-DIAGNOSTIC CHECK	New	384.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,524.00</b>	<b>9,907.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >