

ASS. REC. BY: bel

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 8337R

at Workshop m/s

of

Insured:

XE 117L

Policy No.

DMCVSNA00012072100

Claims No.

SNM21D202170/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM8337Ryr Regn: 13 Apr 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Priusc.c. 1798

Colour

whiteA/C: Insured / Std / NI / NA

Sp. Reading

32/493T/Radio: Insured / Std / NI / NA

Eng/No:

ITDKB3FU 403554767

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

U

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15-04-21

Survey held at

W/S4pmDes. of Damages: (Frt) (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/4/2021 @ 12.56pm Revised to Alfred Toh via Merimen.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Formed:

Lump Sum / Other:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Misc. Insp (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

Total:

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: China Taiping Insurance (Singapore) Pte Ltd

Date 15/04/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLM8337R

CHASSIS NO : JTDKB3FU403554767

MAKE / MODEL : Toyota Pirus 1.8 Hybrid

DATE OF ACCIDENT: 14/04/2021

YOUR INSURED VEHICLE NUMBER: XE117L

MILEAGE: 321493 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper / <i>le</i>	1PC	\$ 423.90	\$ 423.90
2	Rear bumper center pad / <i>lot</i>	1PC	\$ 552.30	\$ 552.30
3	Rear bumper RH retainer X <i>San</i>	1PC	\$ 112.70	\$ 112.70
4	Rear bumper LH retainer X <i>San</i>	1PC	\$ 112.70	\$ 112.70
5	Rear bumper reinforcement ?	1PC	\$ 318.80	\$ 318.80
6	Rear bumper underside RH cover ?	1PC	\$ 133.60	\$ 133.60
7	Rear bumper lower cover lot X <i>San</i>	1PC	\$ 303.90	\$ 303.90
8	Rear bumper RH side extension filler ?	1PC	\$ 148.40	\$ 148.40
9	Rear bumper tow cover / <i>scr</i>	1PC	\$ 35.90	\$ 35.90
10	Rear end panel ?	1PC	\$ 356.80	\$ 356.80
11	Front bumper radiator top grille / <i>le</i>	1PC	\$ 331.90	\$ 331.90
12	Front bumper lower radiator grille X <i>MM</i>	1PC	\$ 163.40	\$ 163.40
13	Front bumper / <i>le</i>	1PC	\$ 495.50	\$ 495.50
14	Front bumper RH side bracket X <i>MM</i>	1PC	\$ 56.80	\$ 56.80
15	Front bumper LH side bracket X <i>MM</i>	1PC	\$ 56.80	\$ 56.80
16	Front bonnet / <i>buc</i>	1PC	\$ 938.40	\$ 938.40
17	F/R headlamp ?	1PC	\$ 2,530.10	\$ 2,530.10
18	F/R headlamp retainer ?	1PC	\$ 33.20	\$ 33.20
19	F/L headlamp ?	1PC	\$ 2,530.10	\$ 2,530.10
20	F/L headlamp retainer ?	1PC	\$ 33.20	\$ 33.20
21	Front bumper reinforcement ?	1PC	\$ 691.10	\$ 691.10
22	Front bumper energy absorber ?	1PC	\$ 69.80	\$ 69.80
23	F/R fog lamp X <i>San</i>	1PC	\$ 910.20	\$ 910.20
24	F/L fog lamp X <i>San</i>	1PC	\$ 910.20	\$ 910.20

LIST TOTAL S\$: \$ 12,249.70

25.00% DISCOUNT S\$: \$ 3,062.43

\$ 9,187.28

SPECIAL NETT

1	Rear bumper clips / <i>le</i>	1 SET	\$ 100.00
2	Rear end panel top garnish clips / <i>me</i>	1 SET	\$ 100.00
3	Reverse sensor / <i>DM</i>	1 SET	\$ 260.00
4	Front bumper clips / <i>me</i>	1 SET	\$ 100.00
5	Front number plate / <i>me BT</i>	3 SET	\$ 50.00

Special Nett Total S\$: \$ 610.00

LABOUR CHARGES

- | | | | | |
|---|--|-----|-------------|---------|
| 1 | | | \$ 1,000.00 | 500 |
| | To labour charge for removing rear bumper, rear bumper reinforcement, rear end panel 250 | | | |
| 2 | To respray rear bumper, rear end panel, rear | 220 | \$ 800.00 | 440 |
| 3 | To labour charge for removing front bumper | | \$ 800.00 | 500 |
| 4 | To respray front bonnet, support panel, front | | \$ 800.00 | 440 |
| | To conduct a standard of operating | | | |
| 5 | procedures post scan test as are requirements for hybrid cars upon completion of collision repairs | | \$ 300.00 | (200) ? |
| 6 | To deactivate and activate high voltage hybrid battery as a requirement for safety precautions | | \$ 300.00 | 200 |

LABOUR TOTAL S\$:	\$ 4,000.00
TOTAL S\$:	\$ 13,797.28
7% GST	\$ 965.81
GRAND TOTAL S\$:	<u>\$ 14,763.08</u>

6 Days.

4/5

After repair photos.

One Q: ap - 8288 0282

19/4/21.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: