

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004856/T1VF3E2

Date: 20/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00003512102
Claimant Vehicle No : SGK4748J Insured Vehicle No : PC7559D
Date of Loss: 15/04/2021 Nature of Claim: TP Claim No: SNM21D202167/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGK4748J**
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B3947676
Reg. Date: 13/08/2020 (Man. Year: 2019) Chassis No: GK33433258
Colour: Silver Odometer: 5569 km
Engine Capacity: 1317 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,570.80	2,517.56	9,053.24	78.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,050.00	2,050.00	4,000.00	66.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,620.80	4,567.56	13,053.24	74.08
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	17,620.80	3,650.00	13,970.80	79.29
+ GST 7.00/7.00% (S\$)	1,233.46	255.50	977.96	79.29
Nett Amount (S\$)	18,854.26	3,905.50	14,948.76	79.29

INSPECTION

Date of Assignment: 19/04/2021
Date Inspected: 20/04/2021 Inspected At: 56 Loyang Way 04-04
Estimated Period of Repair: 6.0 days Repairer: AP Automotive Services Pte Ltd

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK4748J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	898.50 FL	*- FL
2	2		*TAILGATE WINDSCREEN MOULDING	Not Necessary	83.00 FL	*- FL
3	1		*TAILGATE LAMP RH	Not Necessary	397.20 FL	*- FL
4	1		*TAILGATE LOGO - HONDA	Not Necessary	59.20 FL	*- FL
5	1		*TAILGATE EMBLEM - FIT	Not Necessary	65.95 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	127.60 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Cut	105.75 FL	*105.75 FL
8	1		*TAIL LAMP RH	N/S NotNecessary/O/S Cracked	880.60 FL	*325.00 FL
9	1		*TAIL LAMP PANEL RH	Bent	112.00 FL	*112.00 FL
10	1		*REAR BUMPER	Deformed	510.90 FL	*510.90 FL
11	1		*REAR BUMPER CENTER GARNISH	Not Necessary	97.90 FL	*- FL
12	1		*REAR BUMPER LOWER GARNISH RH	Cracked	39.80 FL	*39.80 FL
13	1		*REAR BUMPER RETAINER RH	N/S NotNecessary/O/S Necessary	161.40 FL	*80.70 FL
14	1		*REAR FENDER RH	Bent	631.00 FL	*631.00 FL
15	1		*REAR FENDER WINDOW MOULDING RH	Necessary	71.60 FL	*71.60 FL
16	1		*REAR FENDER INNER TRIM RH	Not Necessary	249.60 FL	*- FL
17	1		*REAR FENDER COWLING RH	Deformed	156.90 FL	*156.90 FL
18	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
19	1		*REAR DOOR LOCK RH	Not Necessary	295.90 FL	*- FL
20	1		*REAR DOOR LOCK CATCH RH	Not Necessary	52.00 FL	*- FL
21	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	203.20 FL	*- FL
22	1		*REAR DOOR INNER WEATHERSTRIP RH	Cut	175.80 FL	*175.80 FL
23	1		*REAR ABSORBER RH	Not Necessary	198.00 FL	*- FL
24	1		*REAR BEARING HUB RH	Not Necessary	295.00 FL	*- FL
25	1		*REAR AXLE	Not Necessary	857.20 FL	*- FL
26	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
28	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*10.00 FS
29	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
30	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
32	1		*REAR FENDER SEALANT	Necessary	250.00 FS	*60.00 FS
33	1		*REAR FENDER WINDOW SEALANT	Necessary	120.00 FS	*40.00 FS
34	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*10.00 FS
36	1		*REAR RIM RH	Dented	4,000.00 FS	*600.00 FS
37	1		*REAR TYRE RH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,916.00 2,959.45
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,345.20 441.89

Total Parts (\$\$) 11,570.80 2,517.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	800.00
2	SPRAY PAINT ON AFFECTED AREAS	New	800.00	800.00
3	TO RNR REAR WINDSCREEN	New	400.00	0.00
4	TO RNR REAR FENDER WINDOW	New	300.00	60.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION }	New	150.00	30.00
6	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
7	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
8	TO CHECK WATER LEAK	New	150.00	30.00
9	TO RNR FUEL TANK	New	250.00	0.00
10	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
11	TO RNR REAR TAILGATE MECHANISM	New	350.00	0.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
13	TO PERFORM RUST PROOFING	New	400.00	30.00
14	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
15	TO RNR UNDERCARRIAGE	New	250.00	100.00
16	TO CHECK WHEEL BALANCING	New	250.00	30.00
Gross Labour Cost (\$\$)			6,050.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >