

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

TPVD UNKNOWN UNKNOWN (SML1264G)

Date of Loss

8 January 2021

Time of Loss

9:50

Loss Description

SH6566C (INSD) WHIL REVERSING HIT
PARKED SML1264G (TP)

Comment

Workshop Details

Total Rebate
Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SML1264G

Registration State SINGAPORE

Mileage 85549

Purchase Date DD/MM/YYYY



Registration Date * 13/12/2011



Age of Vehicle 9

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2011

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION





Driver Name

LEE WAN RONG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD UNKNOWN	<input type="text" value="MERCEDES BENZ"/>
Model	UNKNOWN	<input type="text" value="C 180 KOMPRESSOR"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="WDD2040452A641882"/>
Engine No		<input type="text" value="27191031350495"/>
Engine Capacity		<input type="text" value="1597"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth		<input type="text" value="DD/MM/YYYY"/> 
Age	0	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	TBC	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

225/40ZR18

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Spare wheel

Rear Tyre Size

225/40ZR18

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part supplied by
P
a
r
t
S
u
p
p
l
i
e
d
b
y

A
X
A

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition




Taxes & Ratio





Parts & Labour

Miscellaneous

Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	# (
	0	1		REAR LH SHOCK ABSORBER (NOT CONSISTENT WITH THE IMPACT)		0	0	No	0	0	0	0	0	[
	0	1		REAR LH WHEEL CARRIER (NOT CONSISTENT WITH THE IMPACT)		0	0	No	0	0	0	0	0	[
	0	1		REAR LH WHEEL BEARING HUB	Serviceable	0	0	No	0	0	0	0	0	[

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	PAINT
	0	1		REAR LH WHEEL BEARING (NOT CONSISTENT WITH THE IMPACT)		0	0	No	0	0	0	0	0	1
	0	1		REAR LH DOOR	Replaced	0	1910	No	0	10	0	0	1719	1
	0	1		REAR LH DOOR SEAL / GASKET	Replaced	0	198	No	0	10	0	0	178.2	1
	0	1		REAR LH FENDER	Repair	0	0	No	0	0	0	0	0	1







Labour









Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CHECK DOOR WIRING AND ELECTRICAL COMPONENTS FOR CONDITION	0	20	0	0	Reviewing		
	0		TO APPLY ANTI-RUST UNDERCOAT	0	30	0	0	Reviewing		
	0		TO DISMANTLE AND REPLACE THE DAMAGED LEFT HAND SUSPENSION AND UNDERCARRIAGE PARTS	0	0	0	0	Deny		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO CONDUCT COMPUTERISED 4- WHEELS ALIGNMENT TO ALIGN WHEELS	0	0	0	0	Deny		
	0		TO CONDUCT COMPUTERISED 4- WHEELS ALIGNMENT TO ALIGN WHEELS	0	0	0	0	Deny		
	0		LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS	0	300	0	0	Reviewing		
	0		SPRAY PAINTING CHARGES TO PAINT THE REAR LH DOOR, REAR LH FENDER AND NECESSARY AREAS	0	600	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS OF
REPAIR : 4
DAYS

Reviewing

0

0



0



REAR LH
SPORT RIM
(18 INCH
(NOT
CONSISTENT
WITH THE
IMPACT)

Deny

0

0



EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR LH TYRE	Deny	0	0	NOT NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,847.20
------------------------	--------	-----------------------	------------

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

Labour

Spare Parts

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

2300





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$2,300.00
------------------------	--------	-----------------------	------------

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

Submit for Review