

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21004864/UVF3E2

Date: 03/08/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/20-512655-WTT
Claimant Vehicle No :	SMR2248R	Insured Vehicle No :	FBC1412Z
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR2248R	Engine No:	B4204T111453134
Make & Model:	VOLVO XC60, 2.0 T5 (A)	Chassis No:	YV1DZ40LDG2875429
Reg. Date:	22/02/2016 (Man. Year: 2015)	Odometer:	112965 km
Colour:	Grey		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,938.20	16,592.06	9,346.14	36.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,830.00	1,610.00	46.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,378.20	18,422.06	10,956.14	37.29
+ GST 7.00/7.00% (S\$)	2,056.47	1,289.54	766.93	37.29
Nett Amount (S\$)	31,434.67	19,711.60	11,723.07	37.29

INSPECTION

Date of Assignment:	19/04/2021		
Date Inspected:	10/05/2021	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Aug 2021)
Parts:	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR2248R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Buckled	3,952.00 F	*3,647.40 FL
2	1		*FRONT BONNET INSULATION SHIELD	Not Necessary	855.00 F	*- FL
3	1		*SET FRONT BONNET INSULATION CLIPS	Necessary	114.00 F	*90.00 FL
4	1		*FRONT BONNET LOCK LH	Not Necessary	256.50 F	*- FL
5	1		*FRONT BUMPER FASCIA	Distorted	3,173.00 F	*2,054.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	90.00 F	*68.00 FL
7	2		*FRONT BUMPER SIDE RETAINER L&R	Not Necessary	205.20 F	*- FL
8	2		*HEADLAMP L&R	Cracked	4,053.70 F	*4,053.70 FL
9	1		*HEADLAMP BRACKET LH	Not Necessary	180.50 F	*- FL
10	1		*HEADLAMP WASHER COVER LH	Missing	47.50 F	*47.50 FL
11	1		*HEADLAMP WASHER NOZZLE JET LH	Not Necessary	209.00 F	*- FL
12	1		*FRONT GRILLE BASE }	Cracked	988.00 F	*825.80 FL
13	1		*FRONT GRILLE CHROME }		969.00 F	*- FL
14	1		*FRONT GRILLE EMBLEM }		102.60 F	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Torn	152.00 F	*152.00 FL
16	2		*FRONT BUMPER GARNISH L&R	Torn / Missing	228.00 F	*186.00 FL
17	1		*FRONT BUMPER LOWER COVER	Distorted	171.00 F	*171.00 FL
18	1		*FRONT FENDER LH	Repair	1,482.00 F	*- FL
19	1		*FRONT FENDER COWLING LH	Not Necessary	285.00 F	*- FL
20	1		*SET FRONT FENDER COWLING LH CLIPS	Not Necessary	95.00 F	*- FL
21	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,862.00 F	*1,433.90 FL
22	1		*FRONT BUMPER LOWER COVER INNER	Cracked	627.00 F	*472.90 FL
23	1		*FRONT FOG LAMP LH	Not Necessary	608.00 F	*- FL
24	1		*INTERCOOLER	Punctured	1,026.00 F	*823.60 FL
25	1		*AIR GUIDE LH (TOP)	Torn	75.20 F	*75.20 FL
26	1		*AIR GUIDE LH (LOWER)	Torn	79.80 F	*78.20 FL
27	1		*HORN LH	Cracked	125.40 F	*78.50 FL
28	1		*FRONT FENDER COWLING RH	Not Necessary	304.00 F	*- FL
29	1		*CROSS MEMBER	Bent	494.00 F	*185.40 FL
30	1		*FRONT BUMPER SUPPORT	Bent	250.70 F	*250.70 FL
31	1		*SET FRONT FENDER COWLING SCREW	Not Necessary	100.00 F	*- FL
32	1		*WASHER TANK	Deformed	110.20 F	*102.90 FL
33	3		*FRONT BUMPER LOWER COVER CLIPS	Necessary	18.00 F	*17.10 FL
34	1		*RADIATOR ASSY	Holder Cracked	766.10 F	*766.10 FL
35	1		*AIR-CON CONDENSER ASSY	Punctured / Bent	1,621.20 F	*1,621.20 FL
36	2		*RADIATOR TOP RETAINER L&R	Cracked	20.40 F	*20.40 FL
37	1		*AIR-GUIDE LH (LOWER)	Torn	78.20 F	*78.20 FL
38	1		*HEADLAMP LOWER BRACKET LH	Cracked	113.00 F	*113.00 FL
39	1		*SET FRONT NUMBER PLATE CHROME TYPE	Cracked	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	25,938.20	17,462.70
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	870.64
Total Parts (S\$)	25,938.20	16,592.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT, RENEW, KNOCKING & WELDING FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER LH, REMOVE & INSTALL ALL DAMAGED PARTS, STRAIGHTEN & RE-ALIGN BODY	New	1,380.00	850.00
2	TUFF-KOTE ON DAMAGE PARTS	New	120.00	50.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	1,880.00	900.00
4	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	30.00
Gross Labour Cost (S\$)			3,440.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >