

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 694M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT (CONSISTENT)	BENT / BUCKLED	665.90	665.90
2	REAR BOOT HINGE LH/RH @\$68.50 (CONSISTENT)	NOT NECESSARY	137.00	-
1	REAR BOOT RUBBER (CONSISTENT)	TORN	162.84	162.84
1	REAR BOOT LOCK (CONSISTENT)	BENT	289.50	159.10
1	REAR BOOT LOCK CATCH (CONSISTENT)	NOT NECESSARY	48.85	-
1	REAR BOOT EMBLEM LOGO (CONSISTENT)	NECESSARY	42.60	42.60
1	REAR BOOT EMBLEM VIOS (CONSISTENT)	NECESSARY	48.85	48.85
1	REAR BOOT EMBLEM E (CONSISTENT)	NECESSARY	30.94	30.94
2	REAR TAILLAMP LH/RH @\$481.65 (CONSISTENT)	CRACKED	963.30	963.30
2	REAR TAILLAMP PANEL HOUSING @\$105.00 (CONSISTENT)	TO REPAIR SEE LABOUR	210.00	-
1	REAR BUMPER (CONSISTENT)	DISTORTED	459.75	459.75
2	REAR BUMPER REFLECTOR LH/RH @\$106.25 (CONSISTENT)	CRACKED	212.50	212.50
2	REAR BUMPER BRACKET RH/LH @\$95.50 (CONSISTENT)	NOT NECESSARY	191.00	-
2	REAR BUMPER SIDE HOLDER RH/LH @\$82.50 (CONSISTENT)	BENT	165.00	165.00
2	REAR BUMPER SIDE RETAINER RH/LH @\$89.65 (CONSISTENT)	BENT	179.30	179.30
1	REAR EXHAUST BOX (CONSISTENT)	TO REPAIR SEE LABOUR	569.05	-
2	REAR EXHAUST MOUNTING @\$42.50 (CONSISTENT)	NOT NECESSARY	85.00	-
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	777.25	777.25
1	REAR END PANEL GARNISH (CONSISTENT)	CRACKED	89.65	89.65
1	REAR SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	781.65	-
2	REAR SPARE TYRE PANEL TOOL FOAM LH/RH @\$126.20 (CONSISTENT)	DEFORMED / TORN	252.40	252.40
1	REAR SPARE TYRE PANEL TOOL FOAM -CENTER (CONSISTENT)	NOT NECESSARY	105.00	-
1	REAR SPARE TYRE PANEL CARDBOARD (CONSISTENT)	TORN	156.50	156.50
1	REAR SPARE TYRE SCREW CARRIER (CONSISTENT)	NOT NECESSARY	39.20	-
2	REAR FENDER INNER TRIM LH/RH @\$286.50 (CONSISTENT)	NOT NECESSARY	573.00	-

Report Ref No. CC4/ASM21004891/Ugs3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	REAR FENDER LOWER SHIELD LH/RH @\$58.50 (CONSISTENT)	NOT NECESSARY	117.00	-
	LESS 25% DISCOUNT		-1,838.26	-
	LESS 50% DISCOUNT		-	-2,182.94
			5,514.77	2,182.94
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	CRACKED	280.00	200.00
1	REAR BUMPER SPOILER (SN) (CONSISTENT)	DISTORTED	680.00	600.00
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
			995.00	835.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT ,CUT/WELD REAR PANEL,REAR SPARE TYRE PANEL AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANEL HOUSING ,REAR EXHAUST BOX AND REAR SPARE TYRE PANEL .		1,200.00	900.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		1,100.00	1,000.00
	TO CHECK WIRING .		30.00	30.00
	TO REMOVE,REFIX CUSHION AND INNER TRIM.		120.00	80.00
	TO REPLACE REVERSE SENSOR AND REAR SPOILER .		150.00	50.00
	TO REMOVE,REPLACE REAR EXHAUST BOX .		120.00	60.00
	TO REMOVE ,REFIX FUEL TANK .	NOT NECESSARY	120.00	-
	TO TUFF-KOTE.		90.00	60.00
			2,930.00	2,180.00
	GRAND TOTAL		9,439.77	5,197.94

RECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21004891/Ugs3q2

CHUA KANG SENG

**Licensed Appraiser**