

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21004903/UPS3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800028143
Claimant Vehicle No :	SJC7746B	Insured Vehicle No :	SLX1538R
Date of Loss:	17/04/2021	Nature of Claim:	TP
		Claim No:	9520597547SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC7746B	Engine No:	4G18JP1017
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Chassis No:	JMYSNCS3A8U003400
Reg. Date:	28/02/2008 (Man. Year: 2007)	Odometer:	191907 km
Colour:	Multi-colour		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,705.20	2,481.40	3,223.80	56.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	770.00	960.00	55.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,435.20	3,251.40	4,183.80	56.27
Approved Total (Overridden) (S\$)		2,600.00		

(S\$)	7,435.20	2,600.00	4,835.20	65.03
+ GST 7.00/7.00% (S\$)	520.46	182.00	338.46	65.03
Nett Amount (S\$)	7,955.66	2,782.00	5,173.66	65.03
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		3,144.00		
Global Sum Settlement (S\$)		3,140.00		

INSPECTION

Date of Assignment: 19/04/2021

Date Inspected: 19/04/2021

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SPORT TYRE	Deformed / Torn	1,500.00 FL	*950.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	212.00 FL	*- FL
3	1		*FRONT BUMPER LICENCE PLATE GARNISH	Deformed	85.00 FL	*65.00 FL
4	1		*FRONT GRILLE	Cracked	231.00 FL	*231.00 FL
5	1		*FRONT BUMPER LOWER SPOILER	Cracked	1,800.00 FS	*1,100.00 FS
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
7	1		*FRONT INTER COOLER	Not Necessary	1,800.00 FS	*- FS
8	1		*FRONT BUMPER LICENCE PLATE	Damaged	50.00 FS	*40.00 FS
9	1		*SET FRONT BUMPER SENSOR	Damaged	180.00 FS	*180.00 FS
					Sub Total (\$\$)	5,908.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	202.80
					Total Parts (\$\$)	5,705.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRT BUMPER SENSOR	New	80.00	50.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			1,730.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >