

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004904/T1PS3Q2
Date: 19/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993808
Claimant Vehicle No :	SHD7066Z	Insured Vehicle No :	YN3961L
Date of Loss:	17/04/2021	Nature of Claim:	TP
		Claim No:	2212237931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7066Z		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU421510
Reg. Date:	25/02/2021 (Man. Year: 2019)	Chassis No:	KMHC851CVLU192894
Colour:	Blue	Odometer:	25748 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,244.08	3,239.08	5.00	0.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	970.00	720.00	42.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,934.08	4,209.08	725.00	14.69
+ GST 7.00/7.00% (S\$)	345.39	294.64	50.75	14.69

Nett Amount (S\$)	5,279.47	4,503.72	775.75	14.69
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$125.19/day) (S\$)		250.38		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,861.59		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 19/04/2021

Date Inspected: 19/04/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR ASSY	Bent	1,797.20 FL	*1,797.20 FL
2	1		*REAR LH DOOR ASSY	Bent	1,789.90 FL	*1,789.90 FL
3	1		*FRT DOOR OUTER HANDLE	Cut	234.80 FL	*234.80 FL
4	1		*FRT DOOR OUTER HANDLE COVER	Cut	33.20 FL	*33.20 FL
5	1		*FRT DOOR COMFORTDELGRO LOGO	Necessary	75.00 FS	*75.00 FS
6	1		*REAR APPS LOGO	Necessary	85.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,015.10	4,010.10
- List Item Discount on L Items 20.00/20.00% (\$)	771.02	771.02
Total Parts (\$)	3,244.08	3,239.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	WIRING	New	50.00	0.00
4	TRANSFER DOOR PARTS	New	240.00	120.00
Gross Labour Cost (\$)			1,690.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >