



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103425

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 17/05/2021
Reference CC4/FCI21004906/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 578P
Insured Veh. YL 225J
Claim No. D21001261MFCV/1
Policy No. D-20095987MFCV
Accident Date 17/04/2021
Inspection Date 20/04/2021

Description	Total
Survey Inspection	407.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	407.00
GST (7%)	28.49
Grand Total	435.49

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21004906/R1ra3q2	
			Date: 17/05/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YL 225J	Veh. Inspected	SHC 578P	
Policy No.	D-20095987MFCV	Coverage (\$)	0.00	
Claim No.	D21001261MFCV/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	19/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HATCHBACK	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU303079810	Colour	YELLOW	
Odometer	341812 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOURING	6 mm	
L/H Front Tyre	195/65 R15	TOURING	6 mm	
R/H Rear Tyre	195/65 R15	TOURING	6 mm	
L/H Rear Tyre	195/65 R15	TOURING	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2021	Inspection Date	20/04/2021	
Survey held at	DING AUTOMOTIVE PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 578P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	490.60	490.60
1	FRONT LH BUMPER RETAINER	CRACKED	96.20	96.20
1	FRONT LH HEADLAMP	CRACKED	2,760.51	2,760.51
1	FRONT LH FOG LAMP	SERVICEABLE	970.50	-
1	RADIATOR GRILLE	NOT NECESSARY	398.20	-
1	ENGINE UNDER COVER NO.2	NOT NECESSARY	287.60	-
1	RADIATOR GRILLE LOWER NO.1	NOT NECESSARY	198.60	-
1	FRONT BUMPER LOWER ABSORBER	NOT NECESSARY	148.59	-
1	FRONT BUMPER ENERGY ABSORBER	NOT NECESSARY	138.86	-
1	HEADLAMP COMPUTER	NOT NECESSARY	786.30	-
1	HEADLAMP LEVELLING MOTOR LH	NOT NECESSARY	633.21	-
1	RADIATOR GRILLE EMBLEM	NOT NECESSARY	139.65	-
1	FRONT LH FENDER PANEL	BENT	988.70	988.70
1	FRONT LH FENDER LINER	DEFORMED	213.30	213.30
1	FRONT LH FENDER EMBLEM	NECESSARY	75.86	75.86
1	FRONT LH WHEEL RIM	SCRATCHED	1,655.50	1,655.50
1	FRONT LH TYRE 195/65/15	NOT NECESSARY	265.57	-
1	FRONT LH WHEEL CAP	NOT NECESSARY	285.90	-
1	FRONT LH KNUCKLE ARM	SERVICEABLE	496.50	-
1	FRONT LH KNUCKLE HUB+BEARING	SERVICEABLE	388.40	-
1	FRONT LH LOWER ARM	SERVICEABLE	420.98	-
1	FRONT LH SHOCK ABSORBER ASSY	SERVICEABLE	461.10	-
1	FRONT LH STABILIZER LINK	SERVICEABLE	135.96	-
1	FRONT LH DRIVE SHAFT	SERVICEABLE	1,389.55	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	751.90	-
1	HEADLAMP BRACKET LH	SERVICEABLE	186.90	-
1	FRONT LH BUMPER SIDE BRACKET	SERVICEABLE	198.55	-
	LESS 25% DISCOUNT		-3,740.87	-1,570.17
			11,222.62	4,710.50

Report Ref No. CC4/FCI21004906/R1ra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	85.00	30.00
1	SET FRONT FENDER LINER CLIP (SN)	NECESSARY	75.00	30.00
1	SET RADIATOR GRILLE CLIP (SN)	NOT NECESSARY	70.00	-
1	FRONT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	60.00	-
1	ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	65.00	-
1	RADIATOR GRILLE TOP GARNISH CLIP (SN)	NOT NECESSARY	65.00	-
1	FRONT VEHICLE NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	150.00	-
			570.00	60.00
	<u>LABOUR</u>			
	STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA.		1,100.00	400.00
	TO RUST PROOFING OF THE AFFECTED AREA.		180.00	40.00
	TO REMOVE AND REFIT NECESSARY ITEMS TO FACILITATE REPAIR .	NOT NECESSARY	250.00	-
	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE.		270.00	100.00
	TO TRANSFER FRONT BUMPER MECHANISM TO NEW BUMPER AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO READJUST AND REALIGN HEADLAMP AIM.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE TO ENABLE REPAIR.	NOT NECESSARY	250.00	-
	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT.		130.00	30.00
	TO RESPRAY FRONT BUMPER .		250.00	200.00
	TO RESPRAY FRONT BONNET .	NOT NECESSARY	250.00	-
	TO RESPRAY FRONT LH FENDER PANEL .		250.00	200.00
	TO RESPRAY FRONT LH SIDE MIRROR .		250.00	100.00
			3,500.00	1,070.00
	GRAND TOTAL		15,292.62	5,840.50

Report Ref No. CC4/FCI21004906/R1ra3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00
---	--	--	-----------------

Report Ref No. CC4/FCI21004906/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 578P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 578P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

