

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21004907/R1BS3Q2
Date: 19/07/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMV3940Y	Insured Vehicle No :	SLN4524M
Date of Loss:	15/04/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001684

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV3940Y		
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Engine No:	HR12187394K
Reg. Date:	28/09/2020 (Man. Year: 2020)	Chassis No:	JN1TAAE12Z0985144
Colour:	Red	Odometer:	5466 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,558.96	934.64	624.32	40.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,883.00	1,993.00	1,890.00	48.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,441.96	2,927.64	2,514.32	46.20
+ GST 7.00/7.00% (S\$)	380.94	204.93	176.01	46.20

Nett Amount (\$\$)	5,822.90	3,132.57	2,690.33	46.20
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		150.00		
Nett Liability (\$\$)		3,540.02		

INSPECTION

Date of Assignment: 19/04/2021

Date Inspected: 19/04/2021

Inspected At: 913, Bukit Timah Road
Repairer: Tan Chong Motor Sales Pte Ltd (Bukit Timah)

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jul 2021)
Parts:	144	NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3940Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*GROMMET BUMPER	Necessary	6.80 FS	*6.80 FS
2	2		*GROMMET BUMPER	Necessary	5.40 FN	*5.40 FN
3	1		*ENERGY ABSORBER	Serviceable	125.30 FN	*- FN
4	2		*STAY-RR BUMPER LH/RH	Serviceable	193.80 FN	*- FN
5	1		*BRKT BUMPER LH	Necessary	50.20 FN	*50.20 FN
6	3		*CLIP BUMPER	Necessary	3.90 FN	*3.90 FN
7	1		*FACE -RR BUMPER	Deformed	460.00 FN	*460.00 FN
8	10		*CLIP BUMPER	Necessary	13.00 FN	*13.00 FN
9	1		*EMBLEM	Necessary	79.90 FN	*79.90 FN
10	1		*EMBLEM -BACK DOO	Necessary	64.90 FN	*64.90 FN
11	6		*CLIP CLOSING	Necessary	8.40 FN	*8.40 FN
12	1		*CLOSING PLATE -RR LH	Serviceable	48.80 FN	*- FN
13	1		*CLIP C/LAMP	Necessary	2.80 FS	*2.80 FS
14	1		*GROMET C/LAMP	Necessary	4.90 FN	*4.90 FN
15	1		*GROMET C/LAMP	Necessary	4.90 FN	*4.90 FN
16	1		*LAMP COMB RR,LH	Scratched	435.80 FN	*435.80 FN
17	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
18	1		*SENSOR -REVERSE	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,858.80	1,160.90
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	299.84	226.26
Total Parts (\$\$)	1,558.96	934.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE /INSTALL & TEST REAR REVERSE CAMERA	New	120.00	120.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	360.00	240.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	0.00
4	REPAIR LH REAR FENDER ,TAILGATE ,END PANEL AND RENEW REAR BUMPER	New	1,600.00	780.00
5	S/PAINT LH REAR FENDER ,REAR BUMPER ,TAILGATE AND END PANEL	New	1,600.00	750.00
6	R/I OR RENEW REVERSE SENSOR	New	55.00	55.00
7	CHECK LIGHTING	New	48.00	48.00
Gross Labour Cost (S\$)			3,883.00	1,993.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >