

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO EMV3940Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 GROMET BUMPER \$3.40 EA X 02 <i>ne</i> /	76881-3VA0A			6.80	/
2 GROMMET BUMPER \$2.70 EA X 02 <i>ne</i> /	63846-5V000	5.40	/		
3 ENERGY ABSORBER ? <i>xsu</i>	85090-5WJ0A	125.30			
4 STAY-RR BUMPER LH/RR \$96.90 EA X 02 ? <i>xsu</i>	H5212-1HMMA	193.80			
5 BRKT BUMPER LH ? <i>ne</i> /	85221-3VA0C	50.20	/		
6 CLIP BUMPER \$1.30 EA X 03 <i>ne</i> /	01553-10501	3.90	/		
7 FACE-RR BUMPER <i>de</i> /	85022-5WJ0H	460.00	/		
8 CLIP BUMPER \$1.30 EA X 10 <i>ne</i> /	01553-09611	13.00	/		
9 EMBLEM <i>ne</i> /	90892-3VA0A	79.90	/		
10 EMBLEM-BACK DOO <i>ne</i> /	90890-3VA0A	64.90	/		
11 CLIP CLOSING \$1.40 EA X 06 <i>ne</i> /	01553-09321	8.40	/		
12 CLOSING PLATE-RR LH ? <i>xsu</i>	78819-5WJ0A	48.80			
13 CLIP C/LAMP <i>ne</i> /	73998-3VA0A			2.80	/
14 GROMET C/LAMP <i>ne</i> /	26557-2U001	4.90	/		
15 GROMET C/LAMP <i>ne</i> /	26557-2U000	4.90	/		
16 LAMP COMB RR, LH <i>soe</i> /	26555-5WK0A	435.80	/		
17 SUNDRIES <i>ne</i> /	NPN			20	100.00 /
18 SENSOR-REVERSE ? <i>xsu</i>	SENSOR			250.00	

SUB TOTAL	1499.20	0.00	359.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)	299.84	0.00	0.00
GRAND TOTAL	1199.36	0.00	359.60
OVERALL TOTAL	1558.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMV3940Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAN	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	/ 120.00 /	
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00 / 240 /	
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00 X 1.5	
4 ZZ/001	REPAIR LH REAR FENDER, TAILGATE, END PANEL AND RENEW REAR BUMPER	1600.00 / 780 /	
5 ZZ/002	S/PAINT LH REAR FENDER, REAR BUMPER, TAILGATE AND END PANEL	1600.00 / 750 /	
6 ZZ/003	R/I OR RENEW REVERSE SENSOR	/ 55.00 /	
7 ZZ/004	CHECK LIGHTING	/ 48.00 /	
TOTAL LABOUR CHARGES		3883.00	

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMV3940Y

TOTAL LABOUR CHARGES	3883.00
TOTAL SPARE PARTS CHARGES	1558.96
GRAND TOTAL	5441.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME
SURVEYED DATE
AUTHORIZED DATE
EXCESS CLAUSE
LIABILITY
REMARKS

Rasul - Hy 90010068
19/04/21 @ 1500 hrs

4 days

0.00
0.00

Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: