

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC21004908/Kpa3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date	27/04/2021	
			Cod	e: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKQ 6277J	Veh. Inspected	SLX 7205L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	20/21/21/VP05/024468	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	19/04/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA JAZZ (A)	c.c	1318	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JHMGK3850JX206309	Colour	METALLIC ORANGE	
	Odometer	39318 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	175/65 R15	DUNLOP	9 mm	
	L/H Front Tyre	175/65 R15	DUNLOP	9 mm	
	R/H Rear Tyre	175/65 R15	DUNLOP	9 mm	
	L/H Rear Tyre	175/65 R15	DUNLOP	9 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S			
5.	General Information				
	Accident Date	16/04/2021	Inspect Date / Time	20/04/2021 ( 10:42 AM )	
	Survey held at	GUAN HIN MOTOR WORKSHOP			
		BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC21004908/Kpa3e2

Inspected By

**KONG SENG CHEONG** 

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**