

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21004909/KPS3Q2  
**Date:** 30/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
<b>Claimant Vehicle No :</b>	SMF766M	<b>Insured Vehicle No :</b>	SFP8688H
Date of Loss:	12/04/2021	Nature of Claim:	TP
		Claim No:	0563291292SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMF766M</b>		
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Engine No:	HRA2638977A
Reg. Date:	26/10/2018 (Man. Year: 2018)	Chassis No:	SJNFEAJ11U2308528
Colour:	Metallic Grey	Odometer:	31334 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,199.59	994.32	2,205.27	68.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	660.00	460.00	200.00	30.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,859.59</b>	<b>1,454.32</b>	<b>2,405.27</b>	<b>62.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		

(S\$)	3,859.59	1,150.00	2,709.59	70.20
<b>+ GST 7.00/7.00% (S\$)</b>	270.17	80.50	189.67	70.20
<b>Nett Amount (S\$)</b>	<b>4,129.76</b>	<b>1,230.50</b>	<b>2,899.26</b>	<b>70.20</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,412.50</b>		

INSPECTION

Date of Assignment: 19/04/2021

Date Inspected: 19/04/2021

Inspected At: City Auto Pte Ltd (HQ)  
160 Sin Ming Drive #05-01,, Sin Ming AutoCity,  
Singapore 575722

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Dented / Warped	1,604.00 FN	*1,104.80 FN
2	1		*LH FRONT DOOR OUTER HANDLE	Repair	120.00 FN	*- FN
3	1		*LH WING MIRROR (WITH MOTOR)	Serviceable	400.00 FN	*- FN
4	1		*FRONT LH RIM (Scratched)	Not Consistent With The Impact	1,000.00 FN	*- FN
5	1		*LH DOOR MIRROR COVER	Serviceable	181.10 FN	*- FN
6	1		*FRONT LH TYRE	Serviceable	225.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>3,530.10</b>	<b>1,104.80</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$)</b>	330.51	110.48
<b>Total Parts (\$)</b>	<b>3,199.59</b>	<b>994.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK JACKOUT DAMAGBED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	300.00	200.00
2	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	300.00	260.00
3	WHEEL ALIGNMENT	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>660.00</b>	<b>460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >