

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21004912/Btce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 05/05/2021 **TOWERSINGAPORE 068811** ATTN: YU DOMINIC YISHAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) SHC 1869T Insured Veh. **SDK 3683D** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M0389Z Excess (\$) 0.00 YU DOMINIC YISHAN **Assign Date** 20/04/2021 Assign From **Vehicle Particulars & Condition** 2. HONDA CIVIC 2.0 Make & Model 1998 c.c HIDDEN 2006 Engine No. Year of Reg. JHMFD26406S200870 SILVER Chassis No. Colour Odometer 272711 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/40 R18 MICHELIN 6 mm **MICHELIN** L/H Front Tyre 225/40 R18 6 mm 225/40 R18 **MICHELIN** R/H Rear Tyre 6 mm MICHELIN L/H Rear Tyre 225/40 R18 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information** 15/04/2021 **Inspect Date / Time** 20/04/2021 (11:19 AM) Accident Date MERLIN MOTOR & ENGINEERING WORKS Survey held at BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-13 AMK AUTOPOINT SINGAPORE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM21004912/Btce2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

LIM TEOW GUAN

M

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days