

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21004913/EBA3Q2  
**Date:** 03/08/2021REFERENCE

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D21MFL0000447   |
| <b>Claimant Vehicle No :</b> | SCY3692R                              | <b>Insured Vehicle No :</b> | SLM4762Y        |
| Date of Loss:                | 18/04/2021                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MFL2021D0001639 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SCY3692R</b>                   | Engine No:  | L15B34100250      |
| Make & Model:               | HONDA JAZZ, 1.5 (A)               | Chassis No: | JHMGK5850KS204458 |
| Reg. Date:                  | 18/04/2019 (Man. Year: 2019)      | Odometer:   | 11713 km          |
| Colour:                     | Yellow                            |             |                   |
| Engine Capacity:            | 1498 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 185/55 R16  | Rear Tyre Size:  | 185/55 R16  |
| Front Left Side:  | Dunlop 5 mm | Rear Left Side:  | Dunlop 5 mm |
| Front Right Side: | Dunlop 5 mm | Rear Right Side: | Dunlop 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 3,466.19          | 438.14            | 3,028.05          | 87.36         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 6,260.00          | 3,070.00          | 3,190.00          | 50.96         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>9,726.19</b>   | <b>3,508.14</b>   | <b>6,218.05</b>   | <b>63.93</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>680.83</b>     | <b>245.57</b>     | <b>435.26</b>     | <b>63.93</b>  |

|   |                  |                 |                 |              |
|---|------------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>10,407.02</b> | <b>3,753.71</b> | <b>6,653.31</b> | <b>63.93</b> |
| <b>+ Loss of Use (6.0 x S\$80.00/day) (S\$)</b> |                  | 480.00          |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>4,233.71</b> |                 |              |

INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 28/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)  
255 ALEXANDRA ROAD  
Singapore 159937**Adjuster:** CHEN TSUE YEE**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 21 Jun 2021)  |
| <b>Parts:</b> 144  | HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SCY3692R) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                | Condition     | Repairer's  | Amount     |
|-----|-----|----------|----------------------------|---------------|-------------|------------|
| 1   | 1   |          | *SUNDRIES                  | Necessary     | 100.00 FS   | *30.00 FS  |
| 2   | 1   |          | *FACE ,FR BUMPER           | Repair        | 372.90 FS   | *- FS      |
| 3   | 1   |          | *LOWER GRILLE ASSY ,FR     | Not Necessary | 118.05 FS   | *- FS      |
| 4   | 1   |          | *GARNISH ASSY ,R.FR.FOG    | Not Necessary | 58.20 FS    | *- FS      |
| 5   | 1   |          | *COVER ,FR TOWING HOOK     | Not Necessary | 5.77 FS     | *- FS      |
| 6   | 1   |          | *GARNISH ASSY ,L,FR.FOG    | Not Necessary | 58.20 FS    | *- FS      |
| 7   | 1   |          | *BEAM COMP,FR. BUMPER      | Not Necessary | 239.77 FS   | *- FS      |
| 8   | 1   |          | *BEAM UPPER ,R.FR. BUMPER  | Not Necessary | 23.85 FS    | *- FS      |
| 9   | 1   |          | *SPACERR,FR.BUMPER         | Not Necessary | 7.80 FS     | *- FS      |
| 10  | 1   |          | *SPACERL,FR.BUMPER         | Not Necessary | 7.80 FS     | *- FS      |
| 11  | 1   |          | *CLIP ,BUMPER<br>(15 PCS)  | Necessary     | 25.87 FS    | *25.87 FS  |
| 12  | 1   |          | *BASE ,FR.GRILLE HOOK      | Not Necessary | 198.45 FS   | *- FS      |
| 13  | 1   |          | *MOLDING UPPER ,FR GRILLE  | Not Necessary | 109.12 FS   | *- FS      |
| 14  | 1   |          | *EMBLEM H                  | Not Necessary | 12.90 FS    | *- FS      |
| 15  | 2   |          | *NUTPUSH 3MM               | Not Necessary | 3.15 FS     | *- FS      |
| 16  | 1   |          | *PANEL ,R.FR. FENDER       | Dented        | 318.82 FS   | *318.82 FS |
| 17  | 1   |          | *FENDER ASSY R.FR          | Crushed       | 63.45 FS    | *63.45 FS  |
| 18  | 1   |          | *CLIP,INNER FENDER         | Not Necessary | 23.10 FS    | *- FS      |
| 19  | 1   |          | *LIGHT ASSY ,R.HEAD        | Not Necessary | 1,248.60 FS | *- FS      |
| 20  | 1   |          | *HUB ASSYFR                | Not Necessary | 103.72 FS   | *- FS      |
| 21  | 1   |          | *BEARING ASSY,FR HUB       | Not Necessary | 106.20 FS   | *- FS      |
| 22  | 1   |          | *DISK ALUMINIUM WHEEL 16X6 | Repair        | 197.02 FS   | *- FS      |
| 23  | 1   |          | *FENDER ASSY ,R.FR         | Not Necessary | 63.45 FS    | *- FS      |

F=Franchise part. S=SpcNett.

**Total Parts (\$)**
**3,466.19**
**438.14**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars                                    | Lab.Type | Repairer's                     | Amount          |
|---------------------|--|----------|--------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                                |                 |
| 1                   | INSPECT FR LIGHTING MECHANISMS & FOCUS         | New      | 180.00                         | 150.00          |
| 2                   | RESET VEHICLE SMART ENTRY SYSTEM               | New      | 650.00                         | 580.00          |
| 3                   | REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON | New      | 2,000.00                       | 1,300.00        |
| 4                   | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS   | New      | 2,000.00                       | 1,040.00        |
| 5                   | REMOVE & REPLACE FR R UNDERCARRIAGE PARTS      | New      | 1,200.00                       | 0.00            |
| 6                   | REMOVE AND RENEW RHF WHEEL/RIM/TYRE            | New      | 50.00                          | 0.00            |
| 7                   | WHEEL ALIGNMENT X4                             | New      | 180.00                         | 0.00            |
|                     |  |          | <b>Gross Labour Cost (S\$)</b> | <b>3,070.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >