

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21001588/UVF3Q2

Date:

14/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMPCSNW00197052000

Claimant Vehicle No : SBY1100H**Insured Vehicle No :**

SJU8627K

Date of Loss: 16/04/2021

Nature of Claim:

TP

Claim No: SNM21D202183C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBY1100H**

Make & Model: HONDA HR-V, 1.5 (A)

Engine No: L15B5672358

Reg. Date: 07/01/2020 (Man. Year: 2019)

Chassis No: JHMRU1810JX202353

Colour: Grey

Odometer: 15799 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,322.97	1,683.07	2,639.90	61.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,160.00	6,785.00	5,375.00	44.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,482.97	8,468.07	8,014.90	48.63
+ GST 7.00/7.00% (S\$)	1,153.81	592.76	561.05	48.63

Nett Amount (S\$)**17,636.78****9,060.83****8,575.95****48.63**INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 26/04/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2021)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBY1100H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBER CR.WINDSCREEN DAMPER	Necessary	18.33 FS	*16.40 FS
2	1		*DAMPERSTD 5X5	Necessary	8.64 FS	*7.73 FS
3	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	18.33 FS	*16.40 FS
4	1		*CAPPIVOT	Necessary	4.94 FS	*4.42 FS
5	1		*FASTENER BW/SHIELD (4 PCS)	Necessary	20.14 FS	*18.02 FS
6	1		*FASTENER B (2 PCS)	Necessary	10.45 FS	*9.35 FS
7	1		*FASTENER AW/SHIELD (2 PCS)	Necessary	7.22 FS	*6.46 FS
8	2		*WINDSCREEN SEALANT	Necessary (1 PCS ONLY)	120.00 FS	*60.00 FS
9	1		*TAIL GATE COMP	Badly Dented	866.97 FS	*773.92 FS
10	1		*LINING ASSYTAILGATE	Not Necessary	137.84 FS	*- FS
11	1		*WEATHERSTRIP TAILGATE	Not Necessary	99.94 FS	*- FS
12	1		*LOCK ASSY ,TAILGATE ASSY	Not Necessary	165.30 FS	*- FS
13	1		*EMBLEMRR	Necessary	14.44 FS	*12.92 FS
14	1		*EMBLEM,RR.I-VTEC	Necessary	15.77 FS	*14.11 FS
15	1		*EMBLEM	Necessary	24.51 FS	*21.93 FS
16	1		*NUTPUSH 3MM (2 PCS)	Necessary	3.99 FS	*3.57 FS
17	1		*FACE ,RR.BUMPER	Deformed	467.87 FS	*418.62 FS
18	1		*CLIP BUMPER (8 PCS)	Necessary	17.48 FS	*15.64 FS
19	1		*REFLECTOR ASSYL.RR	Not Necessary	169.57 FS	*- FS
20	1		*REFLECTOR ASSYR.RR	Not Necessary	169.57 FS	*- FS
21	1		*SPACER,L.RR.BPR S	Not Necessary	17.10 FS	*- FS
22	1		*SPACER,R.RR.BUMPER SIDE	Not Necessary	17.10 FS	*- FS
23	4		*ACT RR SENSOR	Serviceable	320.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*BUZZER ASSYSMART	Not Necessary	61.27 FS	*- FS
25	1		*ANTENNA ASSYL.F	Not Necessary	60.04 FS	*- FS
26	1		*PANEL COMPRR	Repair	378.00 FS	*- FS
27	1		*LINING ASSYRR.PANEL	Not Necessary	44.46 FS	*- FS
28	1		*FACE ,FR.BUMPER	Repair	481.74 FS	*- FS
29	1		*CLIP ,BUMPER (22 PCS)	Necessary	48.07 FS	*43.01 FS
30	1		*SPACER ,L.FR.BUMPER SIDE	Not Necessary	11.11 FS	*- FS
31	1		*SPACER ,R.FR.BUMPER SIDE	Not Necessary	11.11 FS	*- FS
32	1		*BASE ,FR GRILLE	Cracked	221.44 FS	*198.13 FS
33	1		*MOLDING ,FR GRILLE UPPER	Not Necessary	215.65 FS	*- FS
34	1		*EMBLEM H	Necessary	16.34 FS	*14.62 FS
35	1		*NUTPUSH 3MM (2 PCS)	Necessary	3.99 FS	*3.57 FS
36	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
37	1		*GROMME .SCREW 5 (2 PCS)	Necessary	4.25 FS	*4.25 FS
					Total Parts (S\$)	4,322.97
						1,683.07

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
2	REMOVE & RENEW REVERSE SENSORS	New	200.00	160.00
3	BODY JOINT SEALANT	New	100.00	0.00
4	BODY UNDERSIDE COATING	New	100.00	0.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	250.00
7	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
8	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
9	REMOVE & INSTALL RR .WINDSCREEN	New	650.00	650.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	520.00
11	CUT OFF & RENEW RR PANEL .STRAIGHTEN ALIGN	New	3,000.00	1,625.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,800.00	1,560.00
13	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	0.00
14	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	1,500.00	650.00
15	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,200.00	520.00
Gross Labour Cost (S\$)			12,160.00	6,785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >