

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/GRB21004917/EES3Q2

Date:

08/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D21MFL0000447

Claimant Vehicle No : SLT7649K

Insured Vehicle No :

SLM1606K

Date of Loss: 09/04/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001549

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT7649K**

Make & Model: BLUECAR BLUECAR, (A)

Engine No: 0

Reg. Date: 10/11/2017 (Man. Year: 2017)

Chassis No: VL4BCEB4RHT002949

Colour: White

Odometer: 80474 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/55 R14

Rear Tyre Size:

175/55 R14

Front Left Side: Bridgestone 4 mm

Rear Left Side:

Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side:

Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,742.20	3,986.60	1,755.60	30.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,145.00	605.00	34.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,492.20	5,131.60	2,360.60	31.51
+ GST 7.00/7.00% (S\$)	524.45	359.21	165.24	31.51

Nett Amount (S\$)	8,016.65	5,490.81	2,525.84	31.51
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
Nett Liability (S\$)		5,810.81		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 20/04/2021

Estimated Period of Repair: 4.0 days

Inspected At: Indeco Engineers Pte Ltd (Defu)
No. 39 Defu Lane 12
Singapore 539315

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2021)
Parts:	144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT7649K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID GLASS (WCP)	Broken	966.00 F	*966.00 F
2	1		*HATCH PUNINFARINA LOGO (WCP)	Necessary	32.00 F	*32.00 F
3	1		*HATCH PUNINFARINA EMBLEM (WCP)	Necessary	62.00 F	*62.00 F
4	4		*BOOT LID GLASS SCREW COVER (WCP)	Cut (2 PCS ONLY)	72.00 F	*36.00 F
5	4		*BOOT LID GLASS SCREW COVER (WCP)	Necessary	8.00 F	*8.00 F
6	1		*BOOT LID GLASS HINGE ASSY (WCP)	Not Necessary	154.00 F	*- F
7	1		*BOOT LID GLASS DAMPER RH (WCP)	Not Necessary	36.00 F	*- F
8	1		*BOOT LID GLASS DAMPER LH (WCP)	Not Necessary	36.00 F	*- F
9	1		*BOOT LID GLASS LOCK (WCP)	Not Necessary	132.00 F	*- F
10	1		*BOOT LID GLASS LOCK CATCH (WCP)	Not Necessary	55.00 F	*- F
11	1		*BOOT LID GLASS CATCH COVER (WCP)	Not Necessary	35.00 F	*- F
12	1		*REAR BOOT LID STICKER	Necessary	40.00 FS	*40.00 FS
13	1		*REAR WEATHERSTRIP (WCP)	Torn	84.00 F	*84.00 F
14	1		*REAR TRIM (WCP)	Not Necessary	128.00 F	*- F
15	1		*REAR LH TAILAMP ASSY (WCP)	Cut	208.00 F	*208.00 F
16	1		*REAR LH TAILAMP FRAME (WCP)	Cut	267.00 F	*267.00 F
17	1		*REAR BUMPER (WCP)	Broken	1,405.00 F	*1,405.00 F
18	1		*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	82.00 F	*- F
19	2		*REAR BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	86.00 F	*- F
20	2		*REAR BUMPER NUMBER PLATE LIGHT (WCP)	Not Necessary	210.00 F	*- F
21	1		*REAR LH FENDER COVER (WCP)	Not Necessary	194.00 F	*- F
22	1		*REAR BUMPER REFLECTOR LH (WCP)	Not Necessary	125.00 F	*- F
23	1		*REAR LH FENDER INNER SHIELD (WCP)	Not Necessary	154.00 F	*- F
24	1		*REAR FENDER STICKER	Necessary	40.00 FS	*40.00 FS
25	1		*REAR BUMPER MARKETING DECAL	Necessary	180.00 FS	*180.00 FS
26	1		*REAR NUMBER PLATE	Broken	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	4,836.00	3,373.00
					+ Margin on L,N Items 20.00/20.00% (S\$)	906.20	613.60
					Total Parts (S\$)	5,742.20	3,986.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT ,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS	New	1,000.00	625.00
2	TO PUTTY ,RESPRAY REAR FENDER AND REAR BUMPER	New	600.00	400.00
3	TO REPLACE REAR WINDSCREEN GLASS & CLEAN UP SHATTERED GLASS	New	150.00	120.00
Gross Labour Cost (S\$)			1,750.00	1,145.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >