

ASS. REC. BY:

REF:

CS / SMR 21004918 / EUf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJE 6869B

at Workshop m/s John Auto Services

of

Insured: SMB 339J

Policy No.

Claims No. BUS/04/21/5013


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJE 6869B

Yr Regn:

2/5/98

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Airwave

c.c 1496

Colour:

Silv

A/C: Insured / Std / NI / N

Sp. Reading

191665

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

GJ11207754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

7/4/21

D.O.A.

21/4/21

Survey held at

John Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-16K

28/4/2021 Cfmed L/S \$4500, 5 repair days.

(RED \$5,750.70; 56%)

Date/Time, File Pass to?



: Prell. Report



: Final Report

28/4 TYPIST

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Formed:

TP

Lump Sum / L/S

\$4500

1011

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

Date 20/4/21 NO.

(533153218)

(533153218)
 BIK 7, 397-D Woodlands Road
 Yew Tee Industrial Estate
 Singapore 6779-16 HP. 85081258

JOHN AUTO SERVICES

(53315321B)

BLK, E5, 395A WOODLANDS ROAD,
YEW TEE INDUSTRIAL ESTATE,
SINGAPORE 677984

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate
Singapore 677996 HP: 85081258

SSE 6869 B

Date

20/4/21

NO.

Labour Charge.

| | | | |
|-----|--------------------------------------|------------|--------------------|
| 1. | Rear Bumper Sensor Refit | \$ 60.00. | 30 |
| 2. | Wiring fee | \$ 40.00. | 30 |
| 3. | Anti Rust ^{glass} | \$ 60.00. | 30 |
| 4. | Rear RH fender TOP Refit | \$ 80.00. | 50 |
| 5. | Rear under Carriage Remove & Replace | \$ 300.00. | ? |
| 6. | Rear Boot interior Remove & Refit | \$ 100.00. | 50 |
| 7. | 2 time wheel alignment | \$ 100.00. | 60 |
| 8. | Roof lining Remove & Refit | \$ 100.00. | 30 |
| 9. | To Respray Painting Damage area | \$ 800.00. | 450 450 |
| 10. | To Remove & Replace Cut & Weld | \$ 800.00. | 700 |
| 11. | To Remove & Refit Rear glass | \$ 120.00. | X |

STER CLKK) 83228813

21/4/21, 12.00pm

ML AL

5 days

My AL Sy

JOHN AUTO SERVICES

(53315321B)

Blk 7, 397-D Woodlands Road
Yew Tee Industrial Estate

Singapore 677996 HP: 85081258

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: