



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 8813H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SET FRONT FORK	BENT / TWISTED	200.00	200.00
1	FRONT RIM	WARPED	100.00	100.00
1	FRONT FENDER	DISTORTED	50.00	50.00
1	FRONT DISC BRAKE	BENT	50.00	50.00
1	FORK RUBBER	TORN	30.00	30.00
1	FRONT MASTER CYLINDER	SERVICEABLE	50.00	-
1	FRONT BRAKE CALIPER	SERVICEABLE	50.00	-
1	FRONT WHEEL BEARING	NECESSARY	80.00	80.00
1	HANDLE BAR 7/8"	BENT	80.00	80.00
1	TRIPLE TREE	DAMAGED	150.00	150.00
1	TRIPLE TREE BEARINGS	NECESSARY	50.00	50.00
1	CG125 TANK	DENTED	150.00	150.00
	LESS 10% DISCOUNT		-	-94.00
			1,040.00	846.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SEAT REWRAP (SN)	DAMAGED	180.00	100.00
			180.00	100.00
	<b><u>LABOUR</u></b>			
	TANK PAINTJOB.		200.00	130.00
	LABOUR.		300.00	220.00
			500.00	350.00
	<b>GRAND TOTAL</b>		<b>1,720.00</b>	<b>1,296.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,000.00</b>

Report Ref No. CS/INC21004921/Utf3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.