

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21004928/T1PA3Q2  
**Date:** 08/07/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100485002   |
| <b>Claimant Vehicle No :</b> | SMK7215P                             | <b>Insured Vehicle No :</b> | SLG4090J     |
| Date of Loss:                | 15/04/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 3636624614SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMK7215P</b>                   |             |                   |
| Make & Model:               | MITSUBISHI ATTRAGE, 1.2 CVT (A)   | Engine No:  | 3A92UHR4610       |
| Reg. Date:                  | 23/04/2019 (Man. Year: 2018)      | Chassis No: | MMBSTA13AKH001407 |
| Colour:                     | Silver                            | Odometer:   | 108226 km         |
| Engine Capacity:            | 1193 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/60 R15    | Rear Tyre Size:  | 185/60 R15    |
| Front Left Side:  | GTRadial 6 mm | Rear Left Side:  | GTRadial 6 mm |
| Front Right Side: | GTRadial 6 mm | Rear Right Side: | GTRadial 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 9,183.35          | 4,182.03          | 5,001.32          | 54.46         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,980.00          | 2,540.00          | 2,440.00          | 49.00         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>14,163.35</b>  | <b>6,722.03</b>   | <b>7,441.32</b>   | <b>52.54</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,400.00</b>   |                   |               |

|                                                 |                  |                 |                 |              |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| (S\$)                                           | 14,163.35        | 5,400.00        | 8,763.35        | 61.87        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 991.43           | 378.00          | 613.43          | 61.87        |
| <b>Nett Amount (S\$)</b>                        | <b>15,154.78</b> | <b>5,778.00</b> | <b>9,376.78</b> | <b>61.87</b> |
| <b>+ Car Rental (8.5 x S\$100.00/day) (S\$)</b> |                  | 850.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 7.45            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>6,635.45</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                  | <b>6,600.00</b> |                 |              |

INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 21/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)  
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park  
 Singapore 408934

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition                    | Repairer's  | Amount     |
|-----|-----|----------|----------------------------------|------------------------------|-------------|------------|
| 1   | 2   |          | *REAR NUMBER PLATE LAMP          | Not Necessary                | 110.40 FL   | *- FL      |
| 2   | 1   |          | *REAR NUMBER PLATE WIRE          | Not Necessary                | 74.75 FL    | *- FL      |
| 3   | 1   |          | *REAR BUMPER                     | Deformed                     | 814.20 FL   | *708.00 FL |
| 4   | 1   |          | *REAR BUMPER TOW COVER           | Not Necessary                | 28.75 FL    | *- FL      |
| 5   | 2   |          | *REAR BUMPER SIDE RETAINER       | Necessary                    | 59.80 FL    | *59.80 FL  |
| 6   | 2   |          | *REAR BUMPER REFLECTOR           | Cracked                      | 96.00 FL    | *96.00 FL  |
| 7   | 1   |          | *REAR BUMPER LOWER GARNISH       | Not Necessary                | 419.30 FL   | *- FL      |
| 8   | 2   |          | *REAR BUMPER BRACKET             | Cracked                      | 318.20 FL   | *205.00 FL |
| 9   | 1   |          | *END PANEL                       | Bent                         | 562.30 FL   | *402.00 FL |
| 10  | 1   |          | *END PANEL KEYLESS SENSOR        | Cracked                      | 110.00 FL   | *110.00 FL |
| 11  | 1   |          | *END PANEL TOP GARNISH           | Deformed                     | 104.74 FL   | *104.74 FL |
| 12  | 2   |          | *TAILLAMP                        | Cracked                      | 634.80 FL   | *490.00 FL |
| 13  | 2   |          | *TAILLAMP SEALER                 | Necessary                    | 40.00 FL    | *40.00 FL  |
| 14  | 1   |          | *REAR EXHAUST SILENCER           | Repair                       | 656.65 FL   | *- FL      |
| 15  | 2   |          | *REAR EXHAUST MOUNTING           | Not Necessary                | 64.40 FL    | *- FL      |
| 16  | 1   |          | *REAR EXHAUST HEAT SHIELD        | Not Necessary                | 80.50 FL    | *- FL      |
| 17  | 1   |          | *REAR FENDER INNER TRIM          | N/S Torn / O/S Not Necessary | 363.40 FL   | *181.70 FL |
| 18  | 1   |          | *REAR FENDER                     | O/S Repair / N/S Bent        | 1,664.50 FL | *755.00 FL |
| 19  | 1   |          | *BOOTLID                         | Bent                         | 953.30 FL   | *828.00 FL |
| 20  | 1   |          | *BOOTLID WEATHERSTRIP            | Twisted                      | 170.00 FL   | *170.00 FL |
| 21  | 1   |          | *BOOTLID EMBLEM                  | Necessary                    | 47.15 FL    | *47.15 FL  |
| 22  | 1   |          | *BOOTLID EMBLEM -ATTRAGE         | Necessary                    | 35.30 FL    | *35.30 FL  |
| 23  | 1   |          | *BOOTLID EMBLEM -MIVEC           | Necessary                    | 43.60 FL    | *43.60 FL  |
| 24  | 1   |          | *BOOTLID LOCK                    | Bent                         | 236.90 FL   | *139.00 FL |
| 25  | 2   |          | *BOOTLID LOCK STRIKER            | Repair                       | 23.00 FL    | *- FL      |
| 26  | 2   |          | *BOOTLID HINGE                   | Repair                       | 220.80 FL   | *- FL      |
| 27  | 1   |          | *BOOTLID ABSORBER                | Not Necessary                | 172.50 FL   | *- FL      |
| 28  | 1   |          | *BOOTLID OUTER GARNISH           | Not Necessary                | 159.30 FL   | *- FL      |
| 29  | 1   |          | *SPARE TYRE TOP BOARD            | Cracked                      | 212.75 FL   | *212.75 FL |
| 30  | 1   |          | *REAR FLOOR PANEL                | Repair                       | 1,014.90 FL | *- FL      |
| 31  | 2   |          | *REAR FENDER AIR VENT            | Deformed                     | 103.50 FL   | *103.50 FL |
| 32  | 1   |          | *REAR WINDSCREEN MOULDING        | Necessary                    | 46.00 FL    | *46.00 FL  |
| 33  | 1   |          | *REAR NUMBER PLATE               | Not Necessary                | 80.00 FS    | *- FS      |
| 34  | 1   |          | *SET REAR BUMPER CLIP            | Necessary                    | 40.00 FS    | *30.00 FS  |
| 35  | 1   |          | *SET REAR FENDER INNER TRIM CLIP | Necessary                    | 30.00 FS    | *10.00 FS  |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                     | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 36  | 1   |          | <b>*SET REAR REVERSE SENSOR</b> | Not Working   | 400.00 FS  | *200.00 FS |
| 37  | 1   |          | <b>*REAR REVERSE CAMERA</b>     | Not Necessary | 500.00 FS  | *- FS      |
| 38  | 1   |          | <b>*JOINT SEALANT</b>           | Necessary     | 150.00 FS  | *60.00 FS  |
| 39  | 1   |          | <b>*WINDSCREEN SEALANT</b>      | Necessary     | 150.00 FS  | *60.00 FS  |
| 40  | 1   |          | <b>*FLOOR INSULATOR</b>         | Not Necessary | 120.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>11,111.69</b> | <b>5,137.54</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> | 1,928.34         | 955.51          |
| <b>Total Parts (S\$)</b>                                  | <b>9,183.35</b>  | <b>4,182.03</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                     | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                 |          |                 |                 |
| 1                              | CHECK REAR WIRING AND LIGHTING STYSTEM          | New      | 60.00           | 30.00           |
| 2                              | REMOVE REFIT REAR LINING ,TRIM AND GARNISH      | New      | 200.00          | 60.00           |
| 3                              | REMOVE AND RENEW REAR REVERSE SENSOR            | New      | 150.00          | 30.00           |
| 4                              | REMOVE AND RENEW REAR EXHAUST SILENCER          | New      | 200.00          | 0.00            |
| 5                              | REMOVE AND RENEW FLOOR INSULATOR                | New      | 120.00          | 0.00            |
| 6                              | REMOVE & REFIT FUEL TANK                        | New      | 150.00          | 0.00            |
| 7                              | REMOVE AND RENEW REAR WINDSCREEN                | New      | 150.00          | 120.00          |
| 8                              | TRANSFER PARTS , ATTACHMENT FROM BOOTLID TO NEW | New      | 200.00          | 60.00           |
| 9                              | PANEL BEATING ON AFFECTED AREAS                 | New      | 1,800.00        | 1,000.00        |
| 10                             | SPRAY PAINTING ON AFFECTED AREAS                | New      | 1,800.00        | 1,200.00        |
| 11                             | APPLY ANTI RUST ON AFFECTED AREAS               | New      | 150.00          | 40.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                 |          | <b>4,980.00</b> | <b>2,540.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >