

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21004934/KVF3E2

**Date:** 29/06/2021

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD Policy No: 0999993650

Date of Loss: 07/04/2021

Nature of Claim: OD

Claim No: 6339460042SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG9738K	Engine No:	K9KE628D403982
Make & Model:	MERCEDES-BENZ CITAN, 1.5 CDI MIXTO (A)	Chassis No:	WDF4156052U221537
Reg. Date:	06/12/2017 (Man. Year: 2017)	Odometer:	59408 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,453.10	4,143.10	1,310.00	24.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	1,380.00	1,660.00	54.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,493.10</b>	<b>5,523.10</b>	<b>2,970.00</b>	<b>34.97</b>
<b>- Excess (S\$)</b>	<b>1,900.00</b>	<b>1,900.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,593.10</b>	<b>3,623.10</b>	<b>2,970.00</b>	<b>45.05</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>461.52</b>	<b>253.62</b>	<b>207.90</b>	<b>45.05</b>
<b>Nett Amount (S\$)</b>	<b>7,054.62</b>	<b>3,876.72</b>	<b>3,177.90</b>	<b>45.05</b>

### INSPECTION

Date of Assignment: 20/04/2021

Date Inspected: 20/04/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUPPORT PANEL (WCP)	Cracked	450.00 F	*450.00 F
2	1	*HEADLAMPS ASSY - RH (WCP)	Cracked	580.00 F	*580.00 F
3	1	*FRONT APRON PANEL (WCP)	Serviceable	210.00 F	*- F
4	1	*FRONT APRON CENTRE EMBLEM (WCP)	Not Necessary	58.00 F	*- F
5	2	*FRONT APRON EMBLEM NUTS (WCP)	Not Necessary	14.00 F	*- F
6	1	*FRONT FENDER - RH (WCP)	Buckled	320.00 F	*320.00 F
7	1	*FRONT FENDER INNER SHIELD - RH (WCP)	Serviceable	185.00 F	*- F
8	20	*FRONT FENDER INNER SHIELD CLIPS - RH (WCP)	Necessary	121.00 FS	*50.00 FS
9	1	*FRONT BUMPER (WCP)	Cracked	1,080.00 F	*1,080.00 F
10	1	*FRONT BUMPER INNER FRAME (WCP)	Cracked	125.00 F	*125.00 F
11	1	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	450.00 F	*450.00 F
12	1	*FRONT BUMPER SIDE BRACKET - RH (WCP)	Cracked	42.00 F	*42.00 F
13	1	*FRONT BUMPER TOP PANEL (INNER) (WCP)	Repair	295.00 F	*- F
14	1	*FRONT BUMPER CENTRE GRILLE (WCP)	Cracked	98.00 F	*98.00 F
15	2	*FRONT BUMPER FOG LAMP COVER - RH / LH (WCP)	O/S Cracked / N/S Serviceable	196.00 F	*98.00 F
16	1	*FRONT BUMPER FOG LAMP - RH (WCP)	Serviceable	115.00 F	*- F
17	1	*FRONT BUMPER TOWING COVER (WCP)	Dented	28.00 F	*28.00 F
18	1	*FRONT BUMPER UNDER COVER (WCP)	Serviceable	115.00 F	*- F
19	1	*FRONT NUMBER PLATE	Serviceable	40.00 FS	*- FS
20	1	*FRONT TIE-ROD-RH (WCP) (Supplementary)	Bent	255.00 F	*255.00 F
21	1	*FRONT TIE-ROD END-RH (WCP) (Supplementary)	Bent	195.00 F	*195.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,972.00	3,771.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	481.10	372.10
Total Parts (\$\$)	5,453.10	4,143.10

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, PIPES AND REFILL AIR-CON GAS	New	150.00	100.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN BONNET, RH FRONT FENDER INNER PANEL, FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	500.00
4	TO PUTTY & SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
5	TO RESET AND RE-PROGRAME HEADLAMP FAULT CODE	New	250.00	0.00
6	TO REMOVE AND REFIT RH FRONT UNDERCARRIAGE (Supplementary)	New	280.00	100.00
7	TO CHECK WHEEL ALIGNMENT (Supplementary)	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,040.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >