

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004936/KVF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	Chu Luo Shien	Policy No:	1700029043	
Date of Loss:	17/04/2021	Nature of Claim:	OD	Claim No: 7091002868SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP9968J		
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Engine No:	2ZRR936978
Reg. Date:	25/07/2017 (Man. Year: 2016)	Chassis No:	ZVW508032851
Colour:	Metallic Beige	Odometer:	46694 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,743.31	4,503.46	239.85	5.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,350.00	560.00	29.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,653.31	5,853.46	799.85	12.02
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	6,153.31	5,353.46	799.85	13.00
+ GST 7.00/7.00% (S\$)	430.73	374.74	55.99	13.00
Nett Amount (S\$)	6,584.04	5,728.20	855.84	13.00

INSPECTION

Date of Assignment:	20/04/2021	
Date Inspected:	20/04/2021	Inspected At: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET RH HINGE	Repair	59.90 FL	*- FL
2	1		*FRONT RH HEADLAMP	Cracked	2,558.10 FL	*2,531.60 FL
3	1		*FRONT RH HEADLAMP PANEL	Distorted	220.50 FL	*213.50 FL
4	1		*FRONT BUMPER	Torn	1,547.70 FL	*1,547.70 FL
5	1		*FRONT BUMPER RH SIDE COVER (BLACK)	Serviceable	81.90 FL	*- FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Cracked	82.32 FL	*82.32 FL
7	10		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
8	1		*FRONT BUMPER UNCLIP COVER	Serviceable	144.50 FL	*- FL
9	1		*FRONT WIPER TANK	Dented	182.50 FL	*182.50 FL
10	1		*FRONT RH FENDER	Bent	977.80 FL	*977.80 FL
11	1		*FRONT RH FENDER INNER SHIELD	Cracked	155.10 FL	*155.10 FL
12	10		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	69.60 FL	*69.60 FL
14	1		*FRONT RH FENDER BRACKET	Bent	55.30 FL	*55.30 FL
15	1		*FRONT RH FENDER TRIANGLE COVER	Missing	129.20 FL	*129.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,324.42	6,004.62
- List Item Discount on L Items 25.00/25.00% (\$)	1,581.11	1,501.16
Total Parts (\$)	4,743.31	4,503.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE ELECTRICAL COMPONENTS	New	250.00	80.00
2	TO REPAIR DAMAGES	New	780.00	550.00
3	TO SPRAY PAINTING	New	880.00	720.00
Gross Labour Cost (S\$)			1,910.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >