

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21004939/T1TF3E2

Date: 05/05/2021

REFERENCE

Insured/Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD	Policy No:	D19MFL0005549_01		
Date of Loss:	13/01/2021	Nature of Claim:	OD	Claim No:	MFL2021D0000191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH7332E	Engine No:	YD25426255A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0009120
Reg. Date:	19/09/2018 (Man. Year: 2017)	Odometer:	93384 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,682.00	1,790.00	13,892.00	88.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,095.00	1,460.00	2,635.00	64.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,777.00	3,250.00	16,527.00	83.57
+ GST 7.00/7.00% (S\$)	1,384.39	227.50	1,156.89	83.57
Nett Amount (S\$)	21,161.39	3,477.50	17,683.89	83.57

INSPECTION

Date of Assignment:	20/04/2021	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Date Inspected:	20/04/2021 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$7,973.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 May 2021)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH7332E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	280.00 F	*280.00 FL
2	2		*FRONT BUMPER SIDE RETAINER LH / RH	* Check	150.00 F	*- FL
3	2		*FRONT FOG LAMP GARNISH LH / RH	N/S Not Necessary / O/S *Check	130.00 F	*- FL
4	2		*FRONT FOGLAMP LH / RH	N/S Not Necessary / O/S *Check	460.00 F	*- FL
5	1		*FRONT BUMPER CENTRE GRILLE	* Check	380.00 F	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	* Check	350.00 F	*- FL
7	1		*FRONT BUMPER CENTRE BEAM	* Check	95.00 F	*- FL
8	2		*FRONT BUMPER STAY LH / RH	* Check	100.00 F	*- FL
9	1		*FRONT WINDSCREEN GLASS	Not Necessary	650.00 F	*- FL
10	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	50.00 F	*- FL
11	1		*TOWING COVER	Cut	20.00 F	*20.00 FL
12	1		*FRONT PANEL	Bent	650.00 F	*650.00 FL
13	1		*FRONT PANEL LOWER CENTER	Repair	75.00 F	*- FL
14	2		*FRONT PANEL LOWER LH / RH	Not Necessary	310.00 F	*- FL
15	1		*FRONT GRILLE	Cracked	350.00 F	*350.00 FL
16	1		*FRONT GRILLE LOGO	Necessary	55.00 F	*55.00 FL
17	1		*HEADLAMP LH / RH	N/S Not Necessary / O/S Cut	500.00 F	*250.00 FL
18	1		*WIPER PANEL COVER	Not Necessary	120.00 F	*- FL
19	1		*WIPER MOTOR	Not Necessary	165.00 F	*- FL
20	1		*WIPER LINK ASSY	Not Necessary	220.00 F	*- FL
21	1		*INTERCOOLER	* Check	1,600.00 F	*- FL
22	1		*INTERCOOLER HOSE	* Check	50.00 F	*- FL
23	1		*INTERCOOLER TUBE	* Check	300.00 F	*- FL
24	1		*HORN	* Check	50.00 F	*- FL
25	1		*AIRCON LIQUID PIPE	Not Necessary	320.00 F	*- FL
26	1		*BLOWER MOTOR ASSEMBLY	* Check	600.00 F	*- FL
27	1		*AIRCONDITIONING / HEATER ASSY	* Check	1,800.00 F	*- FL
28	1		*AIR GUIDE LOWER	* Check	50.00 F	*- FL
29	1		*RADIATOR	* Check	650.00 F	*- FL
30	1		*RADIATOR FAN ASSEMBLY	* Check	450.00 F	*- FL
31	1		*CONDENSER & FAN ASSEMBLY	* Check	1,000.00 F	*- FL
32	1		*CORNER PANEL LH / RH	N/S Not Necessary / O/S Bent	390.00 F	*195.00 FL
33	2		*CORNER PANEL GARNISH LH / RH	Not Necessary	1,400.00 F	*- FL
34	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
36	2		*FRONT DOOR CO. REG. STICKER	Not Necessary	50.00 FS	*- FS
37	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*30.00 FS
38	1		*RADIATOR COOLANT	* Check	50.00 FS	*- FS
39	1		*TRANSMISSION FLUID	Not Necessary	80.00 FS	*- FS
40	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
42	1		*IU BRACKET	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,305.00	1,970.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	180.00
+ Margin on L,N Items 10.00/0.00% (\$\$)	1,377.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE (* Check)	New	95.00	0.00
2	TO CUT / WELD DAMAGED PANELS, STRAIGHTEN & PANEL BEAT CHASSIS FRAME & OTHER PANLES, ALIGN DOORS, TO REMOVE & REPLACE DAMAGED PARTS	New	1,800.00	700.00
3	TO SPRAY PAINTING FRONT & LH / RH SIDE PORTIONS	New	1,200.00	700.00
4	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	150.00	30.00
5	TO CHECK AND RECTIFY LIGHTING, WIRING AND ALL ELECTRICAL COMPONENTS	New	150.00	30.00
6	TO CONDUCT DIAGNOSTIC SCAN CHECK & ERASE FAULT CODE (* Check)	New	150.00	0.00
7	TO REMOVE & REFIT RADIATOR, CONDENSER, OTHER COMPONENTS & TOP UP A/C GAS (* Check)	New	150.00	0.00
8	TO REMOVE & REFIT DASHBOARD, BLOWER, EVAPORATOR & OTHER COMPONENTS (* Check)	New	250.00	0.00
9	TO REMOVE AND REPLACE FRONT WINDSCREEN (* Check)	New	150.00	0.00
Gross Labour Cost (S\$)			4,095.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >