

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21004948/BTF3E2

Date: 01/06/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00031082100
Claimant Vehicle No : SLR1754P Insured Vehicle No : YL678K
Date of Loss: 16/04/2021 Nature of Claim: TP Claim No: SNM21D202205/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR1754P
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1974039
Reg. Date: 02/08/2017 (Man. Year: 2017) Chassis No: JTDGG20W10J007365
Colour: Grey Odometer: 47377 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,012.92	6,042.65	11,970.27	66.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	2,570.00	3,810.00	59.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,392.92	8,612.65	15,780.27	64.69
Approved Total (Overridden) (\$\$)		6,900.00		
(\$\$)	24,392.92	6,900.00	17,492.92	71.71
+ GST 7.00/7.00% (\$\$)	1,707.50	483.00	1,224.50	71.71
Nett Amount (\$\$)	26,100.42	7,383.00	18,717.42	71.71

INSPECTION

Date of Assignment: 20/04/2021
Date Inspected: 20/04/2021 Inspected At: Team Autopro Pte Ltd (Sin Ming)
160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
Estimated Period of Repair: 8.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR1754P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,840.20 FL	*929.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*68.00 FL
3	2		*TAILGATE LAMP	Broken	1,518.80 FL	*1,192.00 FL
4	1		*TAILGATE EMBLEM VALVE MATIC	Necessary	98.60 FL	*50.00 FL
5	1		*TAILGATE EMBLEM ELEGANCE	Necessary	72.20 FL	*50.00 FL
6	1		*TAILGATE OUTER CHROME GARNISH	Broken	298.60 FL	*298.60 FL
7	2		*TAILGATE HYDRAULIC DAMPER	Not Damaged	444.20 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Broken	580.10 FL	*450.00 FL
9	1		*TAILGATE WEATHERSTRIP	Torn	329.10 FL	*198.00 FL
10	1		*TAILGATE INNER LOCK	Jammed	409.00 FL	*312.00 FL
11	1		*TAILGATE INNER LOCK STICKER	Not Damaged	38.00 FL	*- FL
12	1		*TAILGATE LOCK SWITCH	No such part	118.40 FL	*- FL
13	1		*TAILGATE ANTENNA SENSOR	Broken	171.60 FL	*120.00 FL
14	2		*TAILGATE HINGE	Not Damaged	196.80 FL	*- FL
15	1		*TAILGATE WIPER MOTOR	Not Damaged	442.00 FL	*- FL
16	2		*TAILGATE NUMBER PLATE LAMP	Not Damaged	134.00 FL	*- FL
17	1		*TAILGATE WINDSCREEN	Not Damaged	1,071.90 FL	*- FL
18	1		*TAILGATE WINDSCREEN MOULDING	Necessary	118.00 FL	*118.00 FL
19	2		*TAILGATE WINDSCREEN SIDE MOULDING	No such part	230.00 FL	*- FL
20	1		*REAR BUMPER	Broken	968.00 FL	*458.60 FL
21	2		*REAR BUMPER SUPPORT BRACKET	No such part	194.20 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	217.20 FL	*189.60 FL
23	1		*REAR BUMPER REFLECTOR	O/S Broken	139.40 FL	*39.00 FL
24	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	536.00 FL	*200.00 FL
25	1		*REAR END PANEL	Dented	827.80 FL	*420.00 FL
26	1		*REAR END PANEL TOP GARNISH	Broken	258.30 FL	*165.80 FL
27	1		*REAR FLOOR PANEL	Not Damaged	1,093.70 FL	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Damaged	850.00 FL	*- FL
29	1		*SPARE TYRE FASTENER	Not Damaged	247.00 FL	*- FL
30	2		*REAR FENDER	Repair	2,826.40 FL	*- FL
31	2		*REAR FENDER INNER TRIM BOARD	Broken	1,359.60 FL	*1,178.00 FL
32	2		*REAR FENDER SIDE GLASS MOULDING	Not Damaged	291.60 FL	*- FL
33	2		*REAR FENDER AIR VENTS	Not Damaged	305.60 FL	*- FL
34	2		*TAILLAMP	Broken	1,796.20 FL	*1,193.60 FL
35	2		*TAILLAMP LOWER BRACKET	No such part	225.40 FL	*- FL
36	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
37	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
38	2		*TAILGATE LAMP SEAL	No such part	120.00 FS	*- FS
39	2		*TAILGATE LAMP CLIPS	Necessary	100.00 FS	*20.00 FS
40	1		*TAILGATE OUTER CHROME GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*20.00 FS
42	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
44	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
45	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*TAILGATE STICKER	Repeated	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
48	2		*REAR BUMPER REVERSE SENSOR SEAL	Not Necessary	96.00 FS	*- FS
49	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
50	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
51	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
52	2		*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
53	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
54	2		*REAR FENDER SIDE GLASS SEALANT	Not Necessary	200.00 FS	*- FS
55	2		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	120.00 FS	*- FS
56	2		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	160.00 FS	*- FS
57	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
58	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
59	1		*REVERSE CAMERA	Not Damaged	480.00 FS	*- FS
60	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,091.90	7,950.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,078.98	1,907.55
Total Parts (\$\$)	18,012.92	6,042.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R REVERSE CAMERA	New	150.00	0.00
5	R&R REAR FENDER SIDE GLASS	New	500.00	0.00
6	R&R FUEL TANK PIPE	New	150.00	0.00
7	CONDUCT WATER LEAK TEST	New	180.00	0.00
8	DIAGNOSTIC RESET FAULT CODE	New	300.00	80.00
9	UPHOLSTERY	New	300.00	0.00
10	CHECK WIRING	New	100.00	30.00
11	PANEL BEATING	New	2,000.00	1,200.00
12	RUST PROOFING	New	200.00	0.00
13	SPRAY PAINTING	New	2,000.00	1,000.00
Gross Labour Cost (\$\$)			6,380.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >